



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79480



CUSTOMER WORK ORDER

WO #: 79480

Customer: 1000 - BASDEN'S AMERICAN RV -

Tag:
Author: BH
Location: 0417 CHECK WORK

Stock #: 11738
Stock Desc: 2026 TT COACHMEN REMOTE 14R
Chassis #: 5ZT2RMCC9TL019711
Serial #: 5ZT2RMCC9TL019711
Mileage: 0
Licence:

Invoice #:
Date In: 04 APR 26
Promised:
Date Sched:
Completed: 17 APR 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER 4 HRS

CAUSE: New pdi

CORRECTION: Brought unit in. Torqued lugnuts to 110ftlbs. Aired tires to 51psi. Jacked unit up to. Heck breaks and ebreaks working on both sides. All clearance and break lights work. Took lp tank off and filled lp tank since it was vacuum purged. Connected to city water. Sink, toilet, and shower work on city. Turned on lp. Range and water heater work on lp. Microwave works. Outlets work. Checked gcfi and tripped with tester and it tripped. Gcfi works. All interior lights work. Ran awning in and out. Fabric looks good awnjng works properly and lights work. Smoke and lp decetor works. Both vent fans work. Ac unit works. All windows and blinds work properly and screens open and closes as the should. Cabinets and drawers are in good condition all open and catch properly. Fabric is in good condition on dinnete cushions. Front vap lights work and light inside compartment works. Ran lp drop test on unit. Held at 12iwc on 50%. Ran leak test at 8iwc for 5mins. Unit passed leak test. Ran flood test on grey tank. Tank sesnors are working as tank shows full. Stablizer jacks work on unit. Ran flood test on black tank and sensors are working properly showing full. Filled frsh tank to 1/3 and ran pump. Pump sends proper pressure and primes. Went to dump valves and checked to see if they hold. Dump valves hold water back and open to let waste out. Did not connect tv becuase unit does not have anetnna. Fridge works. Outdoor shower works on hot and cold.compartment doors lock and close properly. Model and serial numbers taken for ac, furance, water heater, microwave, and range. Could not find model and serial number for fridge. Entry door opens and closes properly. Entry door lock and dead bolt work properly. Walked around outside of unit free of voids or cracks in silicone and bubbles in decal. Griddle and lp line for griddle does work but griddle is missing top. Tried to check 12v system un plugged but unit is missing disconnect key. Added company decals to unit and propane sticker on tank. Manual tougnue jack works. All traps and drains drain properly to tank with no leaks. Water heater works on pump. Stab jacks retract well. Went tonroof and inspected membrane and dicor to all be in good condition. Checked floors and cabinets to be in good condition and checked door under bed to be working properly. Bathroom door opens and closes properly and latches. Shower curtain is free of tears and moves in track correctly. Control board works showing tank levels and battwry levels.

Customer #: 1000
BASDEN'S AMERICAN RV,



Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C



Subtotal for Job #PDINTT: 0.00

W/O: 79480

Job #1 - Warranty

COMPLAINT: UNIT IS MISSING THE BATTERY DISCONNECT KEY.

CAUSE: Disconnected key

CORRECTION: During pdi noticed disconnected key was missing on battery disconnect. Pictures taken parts request submitted.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	9.75
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	9.75

Parts

Part #	Description	Qty	Price	Total
F100690275	REPLACEMENT KEY ONLY W/ PLUG FOR A23	1.00	2.04	2.04

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JOBS 1,2	1.00	16.83	16.83

Subtotal for Job #1: 38.37

Job #2 - Warranty

COMPLAINT: UNIT IS MISSING GRILL TOP ON GRIDDLE.

CAUSE: Griddle top

CORRECTION: During pdi noticed griddle gas missing top. Pictures taken parts request submitted. Recieved new griddle top. Placed griddle topper in unit with griddle

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
F100503386	GRIDDLE PLATE, 18" LODGE GRIDDLE PLA	1.00	60.06	60.06

Subtotal for Job #2: 60.06

Parts Total: 62.10
 Labour Total: 19.50
 Sublet Total: 0.00
 Extras Total: 16.83

WORK ORDER TOTAL: 98.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 Apr 2026



Customer #: 1000
BASDEN'S AMERICAN RV,

