



Warranty Claim Form

Date: 4/30/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3121S8836242
Transcend 26BHX
Retail Purchase Date: 4/26/2025
Work Started: 4/14/2026
Work Completed: 4/21/2026

Claim Status: Paid
Dealer Work Order #: 13160B
Unit Offline Date: 12/16/2024

Claim #: 982652
Labor: \$238.00
Parts: \$0.00
Shipping: \$0.00
Total: \$238.00

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

ADDISON KRUEGER
9145 102ND ST
WEST ALLIS, Wisconsin 53214
United States
4146149633

Operation Line # 1

Flat Rate Code: 330002 Lines - Fresh Water Line Repair *Fault Code:* Improper Installation/Build

Problem: There was a water line leaking under the unit.

Hours: .2

Cause: A screw holding up the underbelly went through the line. Customer took the underbelly down to repair the line, they replaced the part for a temporary fix, but they need it replaced properly.

Amount: 28.00

Remedy: Customer installed a shark bite in the line; we inspected it and verified the fix was good. It is exactly how we would have completed the repair. We tested and all is good.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 620004 Slide Out Floor Covering - Repair Linoleum (per *Fault Code:* Improper Installation/Build In. ft., including attachments)

Problem: There is a part on the floor in the front of the stove that is bunched up. Customer left thinking that it would lay down, but it still has not. Needs looked at for repair.

Hours: 1.5

Cause: Lino in front of the stove is buckled.

Amount: 210.00

Remedy: Need to take the fascia off and trim back the lino so it can lay down.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #: