



# Warranty Claim Form

Date: 4/30/2026

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FM4531N1123308  
Momentum 381MS  
Retail Purchase Date: 6/6/2022  
Work Started: 3/27/2026  
Work Completed: 4/13/2026

Claim Status: Paid  
Dealer Work Order #: 13279  
Unit Offline Date: 5/17/2022

Claim #: 983625  
Labor: \$14.00  
Parts: \$0.00  
Shipping: \$0.00  
Total: \$14.00

Notes: Sg 4/22/26 Case 1009681

### Dealer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Customer Information

Scott Klockziem  
1131 Circle Dr  
Green Bay, Wisconsin 54313-5874  
United States  
920-360-5631

### Operation Line # 1

*Flat Rate Code:* 920017 VISUAL INSPECTION Wall Securement Campaign *Fault Code:* TSB  
for 18k and up Momentum and Solitude Fifth Wheels

*Problem:* service campaign; checking the concerns of excessive frame flex or wall securement  
in the front upper deck.

*Hours:* .1

*Cause:* Check for frame flex of pin box.

*Amount:* 14.00

*Remedy:* No sign of frame flex visible.

*Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*