

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13204B

Date In: 11 APR 26 Author: MGRAY
Promised Date: 25 DEC 26 Stock No: 11165
: Year: 2024
Customer Name: 16708 - ROKUS, SHARON Manufacturer: GRAND DESIGN
Address: 1911 90TH STREET N Brand: REFLECTION 150 SERIES
: WISCONSIN RAPIDS, WI Model: 270BN
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 715-570-9271 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB: 4/11
Purchased Date: 03 APR 25 :
Delivery Date: 29 APR 25 :
InService Date: :
Serial#: 573FR3128R3350305 :

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 2 - UNDERBELLY HAS SOME W   1020   GRAND
        CAUSE:      pics taken before and after sealant was
        CORRECTION: used expanded black foam to seal area's
                   on underbelly needed  REQUEST: .5
                   approved: .3
WARR    COMPLAINT:  WARRANTY REPAIR 3 - IN BATHROOM THERE IS W   1020   GRAND
        CAUSE:      there is good voltage going to the
                   light.  the sensor light is flickering
                   and very dim pics taken
        CORRECTION: will need a new motion sensor light
                   ..... REPLACED MOTION LIGHT, TESTED
                   WELL.  REQUEST:.5 approved: .2
WARR    COMPLAINT:  WARRANTY REPAIR 4 - DS DOG LEASH HOLDER W   1020   GRAND
        CAUSE:      they had two self tapping screws hold
                   dog leash in place that came loose pic
                   taken before and after
        CORRECTION: i had add 3. 1/4 inch bolts with lock
                   washer and secured bracket into place
                   REQUEST: .9 approved: .5
WARR    COMPLAINT:  WARRANTY REPAIR 5 - WHEN FLUSHING          E   16708   ROKUS
        TOILET, WATER IS BUBBLING UP LIKE THE
        VENT IS CLOGGED.
```

Continued on page 2

Work Order : 13204B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   what i found was the 3 ich pipe going to
         black tank was plugged with balls of
         toilet paper
CORRECTION: flushed out the 3 ich pipe going to
         black tank and fill tank twice alot of
         toilet paper and debri make sure the
         customer is using rv toilet paper
         something that breaks down with ease
REQUEST: 2.2 declined - maintenance
WARR    COMPLAINT:  WARRANTY REPAIR 6 - ROOF IS LEAKING TO   W    1020   GRAND
         THE INSIDE. CMR SPOKE DIRECTLY WITH
         DUSTIN AND SHOWED HIM WEHRE LEAK WAS.
CAUSE:   inspection for water leaks
CORRECTION: roof inspection was done rubber membrane
         and all vents and sealants are ok i also
         checked screws in gutter track found no
         rust i also pulled light and vent shroud
         from inside ceiling couldn't find no
         sign of water intrusion i also used
         thermo image camera and a camera to look
         inside ceiling couldn't find leak maybe
         next time if if issues happens again
         have customer get photos REQUEST: .5
         denied

```

```

*****
Job # Part No Description           PARTS           Bill to Qty Price Total
*****
WARR0 82200689 MOTION LIGHT 12 V LED SURFAC W-1020           1    6.85    6.85

```

```

*****
Job# Lab Code Description           LABOUR Mech Bill to Hrs Rate Total
*****
ARR02 Z992 MISC LABOUR CODE (WARR JS W-1020 0.45 140.00 63.00
ARR03 Z992 MISC LABOUR CODE (WARR JS W-1020 0.50 140.00 70.00
ARR04 Z992 MISC LABOUR CODE (WARR JS W-1020 0.00 140.00 0.00
ARR04 Z992 MISC LABOUR CODE (WARR JS W-1020 0.50 140.00 70.00
ARR05 Z992 MISC LABOUR CODE (WARR JS E-16708 2.00 130.00 260.00
ARR06 Z992 MISC LABOUR CODE (WARR JS W-1020 0.00 140.00 0.00

```

```

*****
Job # Excode Description           EXTRAS           bill to Qty Price Total
*****
ARR05 SSE SHOP SUPPLIES - EXTERNAL E-16708 1.00 19.50 19.50

```

Continued on page 3

Work Order : 13204B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	16708	0.00	260.00	0.00	19.50	15.38	294.88
W	1020	6.85	203.00	0.00	0.00	0.00	209.85
	Totals	6.85	463.00	0.00	19.50	15.38	504.73

&k2S
&k0S