



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26264



WO #: 26264

Customer: 70521 - CANSLER, MICHAEL
Address: 727 HIGHTOP RD
MIDWAY, TN
37809

Home Phone: (423) 470-3369

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11060

Stock Desc: 2025 FW FOREST RIVER CEDAR

CREEK 35RL

Model: 35RL

Serial #: 4X4FCRL29SS234285

Chassis #:

Mileage:

Key #: 9750

Req'n #:

License #:

Trim:

Purchase Date: 15 AUG 25

Date In: 24 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 15 AUG 25

Job #1 - Warranty

TRIM LOOSE ON ENTERTAINMENT SLIDE

Subtotal for Job #1: 0.00

Job #4 - Warranty

CHECK AWNING ROLLS UP SLOW AND MAKES ALOT OF NOISE

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: COUCH SEATING IS CHANGING COLOR AND TEARING

CAUSE: MATERIAL IS DEVELOPING COLOR FADED SPOTS ON THE COUCH, WHICH APPEARS TO BE A DEFECT IN MATERIAL.

CORRECTION: REPLACE COUCH
LABOR 1.0

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: THE MATERIAL ON THE BOTTOM CORNER OF THE LEFT SIDE (IF STANDING FACING DOUBLE SEATING) HAS AND IS CONTINUING TO WORSEEN.

CAUSE: MATERIAL ON THE BOTTOM OF SEATING IS TEARING FROM MANUFACTURING DEFECT. MATERIAL WAS NOT WRAPPED CORRECTLY AT THE CORNER AND ALLOWING MATERIAL TO TEAR AND BECOME DAMAGED.

CORRECTION: REPLACE THE LEFT SIDE OF THE RECLINER LABOR .50

Subtotal for Job #6: 0.00

Customer #: 70521
CANSLER, MICHAEL



Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

W/O: 26264

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 24 Nov 2025

Customer Signature : _____

Customer Work
Order



Customer #: 70521
CANSLER, MICHAEL

