

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79479
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11742 - 2026 AVENUE 29RL 7M5FA3327TA013263

VIN: 7M5FA3327TA013263 HIN:

SER#: 7M5FA3327TA013263

Mileage: 0

Work Order Comp: 30 APR 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 04 APR 26

Inv #: 429647

WO # Job # Description JOB INFORMATION

79479	1	TV WONT PICK UP CHANNELS	
		Ran a channel scan on the tv and it wouldn't pick up any channels. Checked that the booster was on. Tried a different tv and still couldn't get any channels. Removed the panel for the coax cable behind the tv and checked connections. Pulled the panel for the booster and checked connections. Went on the roof and removed the mounting screws for the antenna and removed dicor from the edge. Removed the antenna and found the coax cable wasnt hooked up to the antenna Secured the coax to the antenna. Ran a channel scan and the tv picked up channels. Secured the antenna to the roof. Sealed the antenna with dicor.	
79479	3	SEWER CAP CORD IS MISSING	
		Sewer cap is missing the cord that holds it. Replaced with a new cap and cord.	
79479	6	OUTSIDE FAUCET IS LEAKING	
		When running water through the outside shower i noticed water leaking through the quick connect. Went to the parts room and removed new faucet and located the unit on the lot. Removed the original faucet and installed the replacement. Pressurized water system and now the cold water fitting going into the faucet is leaking.	
79479	2	LEFT SPEAKER IS INOP	

Claim : 79479

 WO # Job # Description JOB INFORMATION

 Left speaker is not working. Removed the speaker to check connections. Removed Bluetooth reciever and inspected wiring. Traced wires to labels and found that the left speaker is hooked up to the "B" channel, which would be the outside speakers. This unit does not have outside speakers. Traced the left side "A" speakers wires. Secured the speaker wires to the wires off of the receiver and the speaker is now working, secured speaker to the ceiling. Secured the reciever to the wall.q

79479 4 STAPLES NEED SET ON SLIDE ROOM
 Staples are sticking out on the slide room.
 Set staples and filled holes with putty.

79479 5 GLUE ON THE CORNER OF THE ISLAND
 Glue on the kitchen island.
 Removed glue.

 Part No Job# Description PARTS Qty Price Total

 DCR505LSW-1 1 PW HAPS FREE SELF-LEVELING DICOR 1.00 8.72 8.72
 CMC39463 3 39463 SEWER CAP W/HOSE CONNECTION 1.00 4.63 4.63
 14322 6 Faucet - Outside - Nautilus Cente 1.00 22.75 22.75

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.90 195.00 175.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 195.00 97.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.40 195.00 78.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50

 Excode Job# Description EXTRAS Qty Price Total

 FRT 6 UPS-OUTSIDE SHWR FAUCET 1.00 10.69 10.69

Parts Total: 36.10
 Labour Total: 487.50
 Sublet Total: 0.00
 Extras Total: 10.69

>>>> Claim Total: 534.29

Customer Signature: _____

Date: _____