



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79648
Promised Date:
23 APR 26



CUSTOMER WORK ORDER

WO #: 79648

Customer: 56695 - WHITE, BAILEY -
618-554-6810

Tag:

Author: BH

Location: 0430 CHECK PREAUTH

Stock #: 11644

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 29NM

Chassis #: 4X4TCKE27TK096786

Serial #: 4X4TCKE27TK096786

Mileage:

Licence:

Invoice #:

Date In: 20 APR 26

Promised: 23 APR 26

Date Sched:

Completed: 30 APR 26

Warr. Date: 23 APR 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: New final

CORRECTION: Its was on the showroom. Lug nuts torqued to spec air pressure correct in all 5 tires. Installed a new battery. Running lights and tail lights work properly brakes and Emergency Brakes work properly. I havepower to the tounge jack but it doesn't work and the light doesn't work neither on the jack. Exterior inspection found the window glazing is wavy on side window i got the waves out. Looks good now. Roof inspection looks good. Entry door stairs stop bracket hit the door hinges. So im going to adjust them. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection found light cove off light in back bedroom that i put on. Put water in fresh tank and ran the water pump to flush out the lines water pump works properly. Bathroom faucet is leaking. Water heater works properly. Stove works properly microwave works properly both refrigerators work properly ac works properly furnace works properly. All the lights work properly all the windows and blinds work properly. Access door to rear bedroom striker plate was loose and screw was stripped out causing the striker plate to move. So i shot another screw i. It and the door works properly now. And i adjusted the main entry door and it closes better. Tv antenna works properly

Labor			
Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Hitch work

New hitchwork installation

CORRECTION: Installed the hitch brakets on the camper and put the rest of the hitch in side compartment. Leveled the camper then checked the ball height and matched the truck hitch setup. Connected the truck to the camper adjusted as needed. Left the camper tongue high as the tongue is low to the ground. Connected the safety chains, breakaway cable and 7-way. Tested the running lights.

Labor			
Code	Description	Mechanic	Total



Customer #: 56695
WHITE, BAILEY





Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: TOUNGE JACK IS NOT WORKING

CAUSE: Tounge jack didn't work

CORRECTION: After i put the new battery on this camper i was doing my checks and the tounge jack would not work. So i check the power and the wire had power all the way up to wear it goes into the head of the jack. So i replaced it with a new one. Made my connection and used a heat gun to heat shrink the connector. Jack works properly now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	97.50

Parts

Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	214.50	214.50

Subtotal for Job #1: 312.00

Job #2 - Warranty

COMPLAINT: BATHROOM FAUCET IS LEAKING

CAUSE: Bathroom faucet leaking

CORRECTION: Took factory faucet off. And installed a new faucet. Hooked up the water lines and tested it no leaks. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	97.50

Parts

Part #	Description	Qty	Price	Total
02-3309	BLK MATTE BATHROOM FAUCET 4IN NON ME	1.00	29.73	29.73

Subtotal for Job #2: 127.23

Job #3 - Warranty

COMPLAINT: DOORSIDE REAR ENTRYDOOR LOCK IS BROKEN

CAUSE: Entry door handle.





CORRECTION: Went to unit and saw flap for entry door handle was missing. Removed old entry door handle. Placed new handle in place. Secured with screws and checked to make sure door latches and deadbolt locks. Deadbolt bolt does lock and door latches.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	58.50

Parts

Part #	Description	Qty	Price	Total
08200	LOCK ASSEMBLY-BLACK	1.00	33.44	33.44

Subtotal for Job #3: 91.94

Parts Total: 277.67

Labour Total: 253.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 531.17

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 May 2026

