



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73096
Promised Date:
no add 26



WO #: 73096

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9552 2026 BAY STAR 3114

Serial#: 142198

Chassis#: 1F66F5DN0S0A01277

Miles/Hrs: 1633

Tag#:

Purchased Date:

Warranty Date:

Date In: 27 MAR 26

Time In:

Job #01 - Warranty

COMPLAINT: UNIT WILL NOT START NUMEROUS TIMES. DRAIN ON CHASSIS BATTERY

CAUSE: Started unit in morning with engine running at high idle and overheating. Upon entering vehicle, found all warning lights on dash on. . Parasitic drain emanating from chassis ecu cluster. Multiple warning lights on dash. Recharged chassis battery overnight. Performed test on battery to verify still good. With all components off and coach turned off, chassis battery has a constant drain of 3.7 amps and an intermittent drain of 5.9 amps. Traced drain back to chassis relays controlled by ecu. All coach side tests normally with no drain. Sublet chassis side to Statkus.

CORRECTION: Statkus performed Ford warranty

After returning from chassis shop found parasitic drain on main line from coach to chassis solenoid. The coach side had 2.5 A of drain the chassis site had 1.8 A of constant drain plugged coach into shore power and allowed charge to be applied at solenoid. Only coach side had 14 V chassis side remained at 2 V. Gave solenoid a tap with plastic hammer. Solenoid closed allowing charge to go through to chassis battery 14 V now present at chassis battery. Allow batteries to charge and checked for parasitic drain. Recommend replacement of solenoid to keep occurrence from happening again. Order replace.

Note: Spoke with Jason at Newmar. After explaining diagnosis, it was recommended by Jason to submit claim for solenoid replacement.

4.00hrs

Labor

Job #	Description	Total
01	DRIAN ON CHASSIS BATTERY	N/C

Subtotal for Job #01: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

Customer #: 1000
MYERS "RV" CENTER,
INC.,



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 05 May 2026

Customer Signature : _____

W/O: 73096
Promised Date: 08 APR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Customer Work
Order

