

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2664896
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TUMZ28TB036499
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080B
 ITEM # UMT24RK-80
 DEALER RO # 73014-1
 CLAIM START DATE 05/05/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-66-02-17-000672 Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:10:22 :: Complaint: Front entry door is hanging on striker plate screws Cause: Sticking on striker plate screws Correction: Removed screws flattened out striker plate and install flat head screws

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-101-01-00-001078 Sliding, Pocket Door - Interior/Interior Doors/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:13:01 :: Travel strap pulled out of the wall on barn door. Door pulled outside corner molding off. Scratch on the door from bottom guide. Reinstall travel strap and screwed the screw back into the wall. Removed the barn door by removing the top trim piece 3 screws, unlocking the rollers. Reinstalled the corner molding and puttied the nail holes. Adjusted the bottom guide away from the wall to prevent the door from hitting the trim. Reinstalled the door by locking the rollers into place. Reinstalled the top trim with 3 screws. Attempted to touch up the scratch on the door, tried a touch up marker, would not cover up scratched. Tried using putty stick, and tried actual stain, noting would cover up the scratch. Recommend replacing the door.

Model#	Dlr Sub Hrs	1.50	Sub Labor Amt \$285.00
Serial#	Appr Hrs	1.00	Appr Labor Amt \$190.00

Notes
 flat rate authorized to replace sliding pocket door.
 1.00 authorized per dealer
 Thank you for authorizing this line for the .8. However, replacing the door is not the only thing that needed to be done.

The corner molding was also pulled off and needed to be reinstalled, and the nail holes puttied. The bottom guide was also adjusted and the travel strap was reinstalled.

Is there any way we can get more time on this?

Submitted	Labor Amt	\$323.00	Approved	Labor Amt	\$228.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$323.00		Total	\$228.00

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.