



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26948



WO #: 26948

Customer: 90955 - KNIGHT, WILLIAM
Address: 12300 LONESOME PINE TRAIL
GREENEVILLE, TN
37745

Home Phone: 423-293-1660

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10901

Stock Desc: 2024 FW FOREST RIVER

SANDPIPER 3800RK

Model: 3800RK

Serial #: 4X4FSAP22RJ046562

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 16 NOV 24

Date In: 07 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 16 NOV 24

Job #1 - Warranty

COMPLAINT: CUST IS OUT OF WARRANTY AS OF NOV 25 HOWEVER, THE CUSTOMER COMPLAINED OF THE FLOOR SQUEAKING AND GIVING IN LIVING/KITCHEN AREA FLOOR IS SINKING WHEN WALKED ON

CAUSE: AFTER INSPECTION OF CUSTOMERS ISSUE TECH FOUND THE FLOOR DID NOT HAVE A BRACE INSTALLED AT FACTORY BUILD. THIS IS ALLOWED THE WOOD GLUE TO GIVE AND FLOOR IS NOT STABLE AND WEAK.

CORRECTION: CUSTOMER IS ASKING FOR THE FLOOR TO BE REPAIRED CORRECTLY REMOVE LINO IN THE AREA, RESECURE THE 2 BOARDS CORRECTLY, ADD BRACE TO UNDERNEATH TO STABILIZE FLOOR, REPLACE THE NEEDED LINO FOR THE AFFECTED AREA. LABOR 4.5

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 90955
KNIGHT, WILLIAM



Customer Signature : _____

Date: 07 Apr 2026

