

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12343

Date In: 11 JUL 25 Author: DLUCAS
Promised Date: 31 MAY 26 Stock No: 11320
: Year: 2025
Customer Name: 17067 - WESTRA, JEREMY Manufacturer: FOREST RIVER
Address: N8657 STATE RD 73 N Brand: PUMA DESTINATION
: RANDOPLH, WI Model: 401RLFT
Postal/Zip: 53956 Miles/Hrs: 0
Phone#(res): 920-382-2996 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: JEREMY.WESTERA@WISCONS Tag#: DB:7/22
Purchased Date: 18 JAN 25 :
Delivery Date: 10 APR 25 :
InService Date: :
Serial#: 4X4TPUS2XSP105230 :

Job # Description JOB INFORMATION Type Bill To

SC CUSTOMER REQUESTS SERVICE CALL TO 329 LIONS TAIL E 17067 WESTR
COURT
1 COMPLAINT: CUSTOMER STATES DURING RAIN THE AWNING W 1021 FORES
ARM BRACE SNAPPED AND NEEDS REPLACEMENT,
SECURE AWNING IF NOT SECURE
CAUSE: pics and measurements taken Couldn't
find tag on motor side awning hardware
the pivot arm had broken will need a new
awning arm
CORRECTION: Will need a new awning arm SEE LINE
2 FOR LABOR
2 COMPLAINT: CUSTOMER TO PAY FOR THE LABOR E 17067 WESTR
CAUSE: awning arms replacement. will need a
new awning fabric is stretched pics
taken
CORRECTION: removed the damage awning hardware used
butyl tape on all new hardware holes
for bolts secured hardware and wired
the hardware as well i tested but fabric
is stretched so i added a spacer to
tighten fabric so the awning now closes
all the way
3 COMPLAINT: Transferred to GRV*12343B on 27 MAR 26 W 1021 FORES
Estimate amount was 0.00 BEDROOM WINDOW
SCREEN IS DAMAGED. CAN WE REPLACE
SCREEN. WINDOW ABOVE THE BED, SMALLER OF
THE TWO.
CAUSE: in master bedroom above the bed the

Continued on page 2

Work Order : 12343

```

*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
                screen was damaged just came detached
                from framework of screen
CORRECTION: re attached the screen to framework and
                secured to window now ok

```

```

*****
Job # Part No      Description          PARTS    Bill to   Qty    Price    Total
*****
1      848150044259  AWNING, SOLERA POWER 12V W-1021      1      793.56    793.56

```

```

*****
Job#  Lab Code  Description          LABOUR    Mech Bill to   Hrs    Rate    Total
*****
2  WARR      MANUFACTURER WARRANTY  JS    E-17067    0.50   130.00    65.00
2  Z990      MISC LABOUR CODE (EXTE JS    E-17067    0.11   130.00    14.30
3  Z990      MISC LABOUR CODE (EXTE JS    W-1021     0.00   140.00     0.00
1  WARR      MANUFACTURER WARRANTY          W-1021     0.00   140.00     0.00
2  Z990      MISC LABOUR CODE (EXTE JS    E-17067    0.22   130.00    28.60
2  Z990      MISC LABOUR CODE (EXTE JS    E-17067    0.68   130.00    88.40
2  Z990      MISC LABOUR CODE (EXTE JS    E-17067    0.99   130.00   128.70

```

```

*****
Job #  Excode  Description          EXTRAS    bill to   Qty    Price    Total
*****
SC  SSE      SHOP SUPPLIES - EXTERNAL  E-17067    1.00    24.38    24.38
SC  SC       SERVICE CALL          E-17067    15.00     3.75    56.25

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E  17067           0.00    325.00     0.00    80.63    22.38    428.01
W  1021          793.56     0.00     0.00     0.00     0.00    793.56

Totals          793.56    325.00     0.00    80.63    22.38    1,221.57

```

&k2S
&k0S