

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 12395B

Date In:	28 APR 26	Author:	MGRAY
Promised Date:	31 MAY 26	Stock No:	11258
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	402LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB 4/28
Purchased Date:	17 JAN 25	:	:
Delivery Date:	25 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS2XSP104353	:	:

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - AFTER INSTALLING W 1021 FORES  
SHOWER HEAD AND FAUCET IN SHOWER, THERE  
IS FURTHER ISSUE  
CAUSE: test wh for operation. temperature  
fluctuates alot due to the water  
fixtures in the vanity and kitchen  
faucet. the bathroom vanity works better  
with out the restriction plate in the  
aerator. the kitchen seams to be fine.  
the wh does fluctuates with the incoming  
water pressure increases. when bench  
testing, the wh would would run ok, but  
the temp was low due to the volume of  
water going threwh it. installed wh back  
in unit and adjusted flow valve on the  
back of wh to help increase the  
temperature. AFTER FURTHER DIAG OF THE  
ISSUE WE RECOMMEND REPLACING THE KITCHEN  
FAUCET AS WELL AS TRHE BATHROOM FAUCET.  
THEY ARE NOT ALLOWING ENOUGH FLOW  
CAUSING THE WATER HEATER TO NOT KICK IN  
ON THE TWO FAUCETS. NEED HIGH FLOW  
FAUCETS TO GET FAUCETS TO FUCNTION  
PROPERLY AND LLOW FLOW  
CORRECTION: 1.0HR FOR FAUCET REPLACEMENT 1.3 R&R  
WATER HEATER FOR FR EQUEST TO PULL UNIT  
FOR BENCH TESTING REQUEST 4.1 FOR DIAG  
ON WHICH FAUCETS ARE WORKING PROPERLY

Continued on page 2

Work Order : 12395B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                AND DOING FURTHER TESTING ON THE WHAT
                WAS CAUSING THE ACTUAL ISSUE.   TOTAL
                REQUEST: 6.4

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.00  140.00  0.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.50  140.00  70.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.00  140.00  0.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.00  140.00  0.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.00  140.00  0.00
ARR01 Z992    MISC LABOUR CODE (WARR TD  W-1021  0.00  140.00  0.00
ARR01 W150    FAUCET, R & R           W-1021  0.00  140.00  0.00
ARR01 W150    FAUCET, R & R           W-1021  0.00  140.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1021        0.00   70.00   0.00   0.00   0.00  70.00
Totals       0.00   70.00   0.00   0.00   0.00  70.00

```

&k2S  
&k0S