

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2532135
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TRPU16SB033424
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT192-80
STACY GARCIA		DEALER RO #	72205-1
4618 SOLECITO LOOP		CLAIM START DATE	12/18/2025
Santa Fe, NM 87507		CLAIM END DATE	04/27/2026
USA			
Retail Date of Purchase	06/14/2025	WARRANTY EXPIRATION DATE	06/14/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	60-138-01-00-001537	Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 16:58:14 :: Complaint: Customer states black valve is not fully shutting, waste seeps out past the valve. Cause: Found that the valve is defective Correction: Remove and replace valve				
Model#		Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#		Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes				
	excessive time requested. Time reduced based on photos, description and flat rate.				
	authorized to replace valve as stated				

Part

Line# 1	Item #	Description			
	60P06584A	3" HUB X 3" HUB VALVE ASSY - #T40 REPLACES ODYSSEY *66N4AA*			
	Model #	Serial #	Part tag		0000412004
	Sub Qty	Sub Dlr Price	Sub Freight		\$0.00
	Appr Qty	Appr Dlr Price	Appr Freight		\$0.00
	Notes				

Labor

Line# 2	Operation Code	Operational Description			
	30-95-24-00-000958	Booth Structure - Interior/Dinette/Repair/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:03:20 :: Complaint: Customer states booth end by entry door is loose and wood is delaminating Cause: Delamination Correction: Secure board to frame, but the top delaminating piece has to be ordered and replaced. Piece is 30"Lx2"Wx5/8" Additional Note : stephanie@dealer-advisors.com, 2025-12-18 17:09:24 :: **chose labor code for the securing of the panel, the piece needing replacement is the top piece as shown in the picture**				
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#		Appr Hrs	0.50	Appr Labor Amt	\$95.00
	Notes				
	hello, an hour was already given to repair dinette booth on claim 2331393.				
	authorized to replace top stile				

Part

Line# 1	Item #	Description			
	F100426073	3/4" X 2" STILE - BRIGHTON WHITE *47085898*			

Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$7.08	Sub Freight	\$196.46
Appr Qty	1.00	Appr Dlr Price	\$7.08	Appr Freight	\$196.46

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
30-99-01-00-001018 Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:10:27 :: Complaint: Customer states the blind in the bathroom is frayed on the edge Cause: Fabric is frayed, component failure Correction: Replace shade, 30L x1 2 3/4W

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$47.50
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

excessive time requested. Time reduced based on photos, description and flat rate.
authorized to replace blind

Part

Line# 1	Item #	Description			
	F100571795	SHADE, ROLLER E SERIES BASELINE 14 X 32 DK CHARCOAL **956023**			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$24.53	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$24.53	Appr Freight \$0.00

Notes

Labor

Line# 4 **Operation Code** **Operational Description**
30-99-01-00-001018 Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:12:27 :: Complaint: Daylight can be seen through the shade Cause: Defective fabric Correction: Replace shade, 31 1/4W x 24L

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$47.50
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

excessive time requested. Time reduced based on photos, description and flat rate.
authorized to replace blind as stated

Part

Line# 1	Item #	Description			
	F100422719	SHADE, ROLLER E SERIES BASELINE 32 X 32- CHARCOAL **956002**			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$38.52	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$38.52	Appr Freight \$0.00

Notes

Labor

Line# 5 **Operation Code** **Operational Description**
20-66-02-17-000672 Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:14:39 :: Complaint: Customer states the entry door is difficult to lock and pops open Cause: Lock is binding on the striker, screws on striker plate are making contact with the screen door and entry door Correction: Moved striker plate and adjust screws by tapping lightly on the screw head to allow enough clearance

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

Submitted	Labor Amt	\$418.00
	Parts & Freight	\$283.08
	Total	\$701.08

Approved	Labor Amt	\$266.00
	Parts & Freight	\$283.08
	Total	\$549.08

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	