

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13295B

Date In:	21 APR 26	Author:	KOTT
Promised Date:	25 DEC 26	Stock No:	11586
:	:	Year:	2026
Customer Name:	9832 - HINTZ, CRAIG	Manufacturer:	FOREST RIVER
Address:	5231 JORDAN ROAD	Brand:	FLAGSTAFF MICRO-LITE
:	STEVENS POINT, WI	Model:	25MBR
Postal/Zip:	54481	Miles/Hrs:	0
Phone#(res):	715-347-4253	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	cjchip@charter.net	Tag#:	DB: 4/22
Purchased Date:	27 MAR 26	:	:
Delivery Date:	20 APR 26	:	:
InService Date:	:	:	:
Serial#:	4X4TFLB25TZ201155	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Fabric floor covers  W    1021  FORES
        under recliners has stains
        CAUSE:      Stained from mfg
        CORRECTION: Used quick solve to remove the spots
        REQ: .10
WARR    COMPLAINT:  WARRANTY REPAIR 3 - panel that covers    W    1021  FORES
        water pump the screw has cracked the
        bottom piece that screws into the floor
        CAUSE:      Improper install from mfg , the board
        was broken from the screw being put to
        close to edge
        CORRECTION: Removed the board and staples then cut
        new piece drilled a hole then secured
        the board to panel with staples
        reinstalled to cover the water pump
        REQ: .20
WARR    COMPLAINT:  WARRANTY REPAIR 4 - The water heater not W    1021  FORES
        working on electric
        CAUSE:      There was a wire touching metal inside
        the reset buttons on exterior of water
        heater
        CORRECTION: I tried a new electric element after
        finding if I disconnected wires from it
        there was no issue but that did nothing
        , I then removed the exterior tstat
        cover and found wire touching metal case
        in one area pushed it off the metal then
        retested breakers no longer trip and
```

Continued on page 2

Work Order : 13295B

```

*****
Job #      Description          JOB INFORMATION          Type Bill To
*****
                water heater works    REQ: .30

```

```

*****
Job # Part No Description          PARTS          Bill to    Qty    Price    Total
*****
WARR0 145856  SUBURBAN 120V ELEMENT          W-1021        0    12.56    0.00

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50   140.00   70.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.00   140.00    0.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.00   140.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1021    0.50   140.00   70.00

```

```

*****
Job #  Excode    Description  EXTRAS          bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021        0.00    210.00    0.00    0.00    0.00    210.00

                Totals        0.00    210.00    0.00    0.00    0.00    210.00

```

&k2S
&k0S