

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2658863
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKZ22TK097628
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT24RRT-94
JEFFERY O'MILLIAN		DEALER RO #	79752
8615 NORTHFIELD DR		CLAIM START DATE	04/29/2026
Evansville, IN 47711		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/18/2025	WARRANTY EXPIRATION DATE	10/18/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-43-19-00-001109	Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-29 13:29:58 :: CUSTOMER ADVISES THAT RAIN RUNS DOWN BETWEEN THE AWNING FABRIC AND THE OUTER TRAILER WALL Additional Note : bhoffman@americanrvcenter.com, 2026-04-29 13:33:42 :: Seal between camper and awning rail is bad Silicone awning rail			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$39.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-138-01-00-001521	Termination Valve - 3" or 1.5" (Read Notes!!!) - Plumbing/Drainage System/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-29 13:30:22 :: CUSTOMER ADVISES THAT THERE IS A LEAK COMING FROM THE DUMP VALVE FOR THE BLACK TANK. Valve is not sealing Replace valve seals Additional Note : bhoffman@americanrvcenter.com, 2026-04-29 13:35:53 :: WE ARE NOT REPLACING THE VALVE ONLY THE SEALS THANK YOU			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$39.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	40-106-01-12-001221	Tail Light Assembly - Surface Mount, each - Electrical/12 Volt Exterior/Replace/ Exterior Lighting		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-29 13:32:29 :: REPLACE TAIL LIGHT LENSE. Lens missing/broken Installed new lense			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$39.00
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
---------	----------------	-------------------------	--	--

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-04-29 13:33:13 :: VACUUM BREAKER IS LEAKING Valve leaking Remove and replace valve

Model#Dlr Sub Hrs0.30Sub Labor Amt \$58.50

Serial#Appr Hrs0.30Appr Labor Amt\$58.50

Notes

Submitted	Labor Amt	\$175.50	Approved	Labor Amt	\$175.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$175.50		Total	\$175.50

DEALERDATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMERDATE

SIGNATURE

All repairs described have been inspected and are satisfactory.