



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79639



Customer #: 56598
GOEBEL, DAVID



CUSTOMER WORK ORDER

WO #: 79639

Customer: 56598 - GOEBEL, DAVID -
812-430-9916

Tag:

Author: BH

Location: 0422 CHECK PREAUTH

Stock #: 11693

Stock Desc: 2026 TT COACHMEN APEX
242BARV

Chassis #: 5ZT2CXNB0TS049693

Serial #: 5ZT2CXNB0TS049693

Mileage:

Licence:

Invoice #:

Date In: 20 APR 26

Promised:

Date Sched:

Completed: 23 APR 26

Warr. Date: 28 MAR 26

Job #1 - Warranty

COMPLAINT: ONE OF THE LIGHTS OVER THE BED IS NOT WORKING

CAUSE: Light not working.

CORRECTION: Brought unit in. Connected to shore power and ran out slideroom to access bedroom. Went to bedroom and saw light wasn't working. Removed cover and screws from light. Saw quick connect on positive wires. Wires had loose connection. Used crimp to put wires together and made a good connection to power light on. Placed light back up and screwed into place after putting wires back up channel. Placed cover on light. Light now works.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	48.75
Subtotal for Job #1:			48.75

Job #2 - Internal

COMPLAINT: THE CO DETECTOR KEEP GOING OFF

CAUSE: Lp leak

CORRECTION: Customer said when running furnace lp detector would go off. Ran furnace for 30 mins and detector did not go off. Left lp tank open but turned off furnace. Left on and checked throughout day to see if detector was going off. After sitting for a day detector did not go off. Could not replicate customer problem.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
LP20	20 LB. LP CYLINDER	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Warranty

COMPLAINT: WHEN FLUSHING THE BLACK TANK IT WAS FILLING THE UNDERBELLY AND LEAKING IN THE UNIT

CAUSE: Black tank flush

CORRECTION: Brought unit in. Connected to black tank flush and ran water through it. While running went inside and saw line had been split and was leaking water all under shower leaking into under belly. Cut off line that was cut. Added couplers on both sides of line and place new line in. Crimped new line in place with



cuppler and ran water through line. And no leaks found. Closed shower back up after drying

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	78.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	19.50

Parts

Part #	Description	Qty	Price	Total
C01292790	1/2" BLUE PVC HIGH PRESSURE HOSE	1.00	0.27	0.27
4395521	1/2" PEX COUPLING	2.00	2.34	4.68

Subtotal for Job #3: 102.45

Parts Total: 4.95
Labour Total: 146.25
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 151.20

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Apr 2026

W/O: 79639



Customer #: 56598
GOEBEL, DAVID

