

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2668941
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEE
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TRPV24TB036637
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT198-80
		DEALER RO #	73116-1
		CLAIM START DATE	05/08/2026
		CLAIM END DATE	01/01/1900
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor				
Line# 1	Operation Code	Operational Description		
	20-66-01-00-000679	Screen Cloth - Exterior/Entry Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-08 09:53:55 :: Complaint: There is a tear in the screen on the screen door Cause: Unknown Correction: Rescreen lower part of screen door			
Model#	Dir Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			
	Excessive time requested. Time reduced based on photos, description and flat rate.			
	Authorized to replace lower portion of screen			

Labor		Operational Description	
Line# 2	Operation Code	Operational Description	
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code	
Complaint, Cause, Correction			
Original Note : stephanie@dealer-advisors.com, 2026-05-08 09:56:24 :: Complaint: Decals are coming off Cause: The decals are peeling Correction: Carefully remove decals so glass does not get scratched, clean the dirt from the window of the front cap. Remove the adhesive with adhesive remover. Clean the window again to place new decal on. Center the decal on the front cap and properly place the new decal where the factory location is.			
Model#	Dlr Sub Hrs	2.00	Sub Labor Amt \$380.00
Serial#	Appr Hrs	1.00	Appr Labor Amt \$190.00
Notes			
Excessive time requested. Time reduced based on photos, description and flat rate.			
Authorized to replace decal			

Labor				
Line# 3	Operation Code	Operational Description		
	60-137-01-00-001513	Thetford Seat & Cover - Plumbing/Toilet (Thetford)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-08 09:57:36 :: Complaint: Toilet lid has a gouge in the top Cause: Gouge in the lid Correction: Will need to remove plastic screws that hold the lid on and replace the lid then reattach			
Model#	not on tag	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	e002advsad597	Appr Hrs	0.30	Appr Labor Amt \$57.00
	Notes			

Submitted	Labor Amt	\$532.00	Approved	Labor Amt	\$304.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$532.00		Total	\$304.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.