



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79837



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 79837

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BH

Location: 0508 CHECK PREAUTH

Stock #: 11749

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 26LP

Chassis #: 4X4TCKB21TK100111

Serial #: 4X4TCKB21TK100111

Mileage: 0

Licence:

Invoice #:

Date In: 06 MAY 26

Promised:

Date Sched:

Completed: 08 MAY 26

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New PDI

CORRECTION: Exterior; Torqued lugs to spec. Adjusted tire pressures to spec. Installed company decals. Installed battery box. Filled and installed LP cylinders. Tested awning function. Tested brakes and breakaway systems. Tested clearance lights. Inspected all exterior doors for fit and finish. Inspected exterior walls and seals. Performed roof inspection. Tested stabilizers. Performed LP drop test.

Interior; Tested interior lights. Checked all cabinets and interior doors. Inspected furniture and bedding. Checked all windows and blinds. Checked water system on pump and city connection. Tested LP and smoke detector. Tested all appliances. Tested entire LP system. Inspected interior walls, ceiling, and floor.

Issues; entry door hard to close. Dicor on roof has multiple voids and is aerated. Water heater door hard to open and close.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE ENTRY DOOR IS HARD TO CLOSE

CAUSE: Striker plate pushed too far in

CORRECTION: Adjusted striker plate out

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00



Subtotal for Job #1: 39.00

Job #2 - Warranty

COMPLAINT: THE DIECORD ON THE ROOF AND MANY VOIDS AND APPEARS TO BE AERATED

CAUSE: Dicor installed very poorly from factory

CORRECTION: Coved all voids and aerated areas

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #2: 39.00

Job #3 - Warranty

COMPLAINT: WATER HEATER DOOR IS HARD TO OPEN AND CLOSE

CAUSE: Door adjusted down and left too far

CORRECTION: Adjusted door up and right as much as possible. OEM Door design limits adjustment

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	0.00

Subtotal for Job #3: 58.50

Parts Total:	0.00
Labour Total:	136.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	136.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 May 2026

W/O: 79837



Customer #: 1000
BASDEN'S AMERICAN RV,

