

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12452

Date In: 25 JUL 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11043
: Year: 2024
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF MICRO-LITE
: CHICAGO, IL Model: 21DS
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: not paid in full- WS C
Purchased Date: 01 FEB 25 :
Delivery Date: 05 MAY 25 :
InService Date: :
Serial#: 4X4TFLW27RD458074 :

Job # Description JOB INFORMATION Type Bill To

SS COMPLAINT: SEASONAL STORAGE E 17609 WOLF
CAUSE: NEED STORE
CORRECTION: STORED
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 17609 WOLF
CONTAINED - TOWABLE
CAUSE: Unit needed winterize
CORRECTION: Unit winterized 10/1/25
SUM COMPLAINT: SUMMERIZE CAMPER AND DEWINTERIZE E 17609 WOLF
CAUSE: Unit needed winterize summerize unit
CORRECTION: Unit winterized 10/1/25 unit summerized.
WARR COMPLAINT: WARRANTY REPAIR 1 - THE BATHROOM FAUCET W 1021 FORES
LEAKS SOMEWHERE BELOW THE SINK. WATER
POOLS ON THE FLOOR IN THE BATHROOM.
UNDER THE SINK THEN RUNS ON TO FLOOR.
CMR BELIEVES THAT THE LEAK IS COMING
FROM THE COLD WATER LINE.
CAUSE: Customer stated bathroom sund has a leak
CORRECTION: Did a water test on it left over night
did not see a leak did a aire pressure
test on it and did not find a leak
request: .5
WARR COMPLAINT: WARRANTY REPAIR 2 - AS YOU ARE SITTING W 1021 FORES
ON THE SOFA, THE LEFT RECLINER MECHANISM
DOES NOT WORK. LEVER IS MOVING, BUT DOES
NOT ENGAE THE FOOT REST
CAUSE: test recliner on left side of sofa.
customer says it won't open the door
rest when the release is pulled.

Continued on page 2

Work Order : 12452

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: tested multiple times and it work.
          couldn't duplicate problem.  REQUEST .5
WARR    COMPLAINT:  WARRANTY REPAIR 3 - THE WINDOW TO THE   W   1021   FORES
          RIGHT OF THE SOFA WHEN SITTING ON IT HAS
          A SCREEN THAT DOES NOT FIT SNUGGLY.
          CAUSE:      check window to the right of sofa for
          gaps in the screen. The inner part of
          the frame is bent on the left side where
          the seam is. May need to replace window.
          CORRECTION: .... REQUEST: 2.0
WARR    COMPLAINT:  WARRANTY REPAIR 4 - STRAP TO PULL OUT   W   1021   FORES
          SOFA TORE LOOSE.
          CAUSE:      sofa strap ripped open the fabric it was
          sewen to. need to repair of replace
          sofa.
          CORRECTION: ... need direction from manu on how to
          repair, or if need replacement.
    
```

```

*****
Job # Part No      Description          PARTS      Bill to      Qty      Price      Total
*****
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON E-17609      0          9.62         0.00
    
```

```

*****
Job#  Lab Code  Description          LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY TD      E-17609      0.00      130.00      0.00
WS W495      WINTERIZE RV (WATER SY JT      E-17609      0.70      130.00      91.00
SUM Z990      SUMMERIZE              JT      E-17609      0.00      130.00      0.00
SUM Z990      SUMMERIZE              TD      E-17609      0.50      130.00      65.00
ARR01 Z992      MISC LABOUR CODE (WARR JT      W-1021      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.50      140.00      70.00
ARR03 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.00      140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.00      140.00      0.00
ARR04 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.21      140.00      29.40
ARR03 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.36      140.00      50.40
ARR03 Z992      MISC LABOUR CODE (WARR TD      W-1021      0.04      140.00      5.60
    
```

```

*****
Job #  Excode   Description          EXTRAS      bill to      Qty      Price      Total
*****
SS  SS        SEASONAL STORAGE          E-17609      1.00      207.00      207.00
SS  SSE       SHOP SUPPLIES - EXTERNAL  E-17609      1.00      11.70      11.70
SS  J-ADJ     QUOTE ADJUSTMENT          E-17609      1.00      -11.70     -11.70
WS  J-ADJ     QUOTE ADJUSTMENT          E-17609      1.00      14.00      14.00
SUM  J-ADJ     QUOTE ADJUSTMENT          E-17609      1.00      -10.00     -10.00
    
```

Continued on page 3

Work Order : 12452

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	17609	0.00	156.00	0.00	211.00	20.20	387.20
W	1021	0.00	225.40	0.00	0.00	0.00	225.40
	Totals	0.00	381.40	0.00	211.00	20.20	612.60

&k2S
&k0S