



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72205
Promised Date:
24 1111 25



WO #: 72205 (Appointment Date: 15 AUG 2025 - Time: 09:15am)

Customer Name: 60041 - GARCIA,
STACY JOE

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9447 2025 R-POD RP-192

Serial#: 4X4TRPU16SB033424

Chassis#: 4X4TRPU16SB033424

Miles/Hrs:

Tag#: 6733

Purchased Date: 14 JUN 25

Warranty Date: 14 JUN 25

Date In: 15 AUG 25

Time In:

Job #1 - Warranty

COMPLAINT: Customer states install bbq rail on door side

CAUSE: REFERENCE WORKORDER: 71911

CORRECTION: Installed grill bracket

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #1-1 - Internal

COMPLAINT: Transferred to RV*72481 on 10 OCT 25

Estimate amount was 0.00

INSTALL BBQ GRILL TRACK

CORRECTION: Had to cut from 10 stick.

Installed track

Labor

Job #	Description	Total
1-1	INSTALL TRACK	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	0.00	N/C	N/C

Subtotal for Job #1-1: 0.00

Job #2 - Internal

COMPLAINT: CUSTOMER STATES WATER HEATER SHOWS INTERMITTENT ERROR CODE..E02

CORRECTION: Could not verify customers concern

Customer #: 60041
GARCIA, STACY JOE





Labor		
Job #	Description	Total
2	WATER HEATER DIAGNOSTIC TIME	N/C
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES BLACK VALVE NOT FULLY SHUTTING..WASTE SEEPS OUT PAST VALVE

CAUSE: DEFECTIVE VALVE

CORRECTION: REMOVE AND REPLACE VALVE
 1.00HRS

Labor		
Job #	Description	Total
3	BLACK TANK VALVE	N/C
Subtotal for Job #3:		0.00

Job #4 - Internal

COMPLAINT: CUSTOMER STATES WATER LEAKING FROM DRIVER SIDE REAR CORNER WHEN CONNECTED TO CITY WATER USING WATER PRESSURE REGULATOR

CORRECTION: UNABLE TO DUPLICATE

Labor		
Job #	Description	Total
4	WATER SYSTEM TROUBLESHOOT	N/C
Subtotal for Job #4:		0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES BOOTH END BY ENTRY DOOR LOOSE AND WOOD DELAMINATING

CAUSE: DELAMINATING

CORRECTION: Secured board to frame, but top delaminating piece has to be ordered. delaminating piece is 30 inches long by 2 inches wide by 5/8 inches thick.
 .50HRS

Labor		
Job #	Description	Total
5	DINETTE BOOTH	N/C
Subtotal for Job #5:		0.00

Job #6 - Internal

COMPLAINT: CUSTOMER STATES SHOWER DOOR DIFFICULT TO SHUT

CORRECTION: UNABLE TO DUPLICATE

Labor		
Job #	Description	Total
6	SHOWER DOOR	N/C
Subtotal for Job #6:		0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES BLIND IN BATHROOM FRAYED ON EDGE

CAUSE: Component failure



CORRECTION: Recommend replacing shade fabric measures 30 inches long by 12 and three-quarter inches wide
.25HRS

Labor		
Job #	Description	Total
7	BLIND	N/C
Subtotal for Job #7:		0.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES DAYLIGHT CAN BE SEEN THROUGH SHADE

CAUSE: DEFECTIVE FABRIC

CORRECTION: Recommend replacement of shade measures 31 1/4 inches wide by 24 inches long
.25HRS

Labor		
Job #	Description	Total
8	SHADE	N/C
Subtotal for Job #8:		0.00

Job #9 - Warranty

COMPLAINT: CUSTOMER STATES ENTRY DOOR DIFFICULT TO LOCK AND POPS OPEN

CAUSE: BINDING ON STRIKER

CORRECTION: Verified customer concern. Screws on striker plate making contact with screen door and entry door. Moved striker plate and adjusted screws by tapping lightly on head allowing enough clearance to operate correctly
.20HRS

Labor		
Job #	Description	Total
9	ENTRY DOOR ADJUST	N/C
Subtotal for Job #9:		0.00

Job #10 - External

CUSTOMER WANTS RECOMMENDATION ON A HIGHER SPARE TIRE CARRIER OR OTHER OPTIONS THAT DONT INTERFERE WITH CARGO RACK ON BACK

Subtotal for Job #10: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

W/O: 72205
Promised Date: 31 JUL 25



Customer #: 60041
GARCIA, STACY JOE



Customer Signature : _____

Date: 16 Dec 2025

W/O: 72205
Promised Date: 31 JUL 25



Customer #: 60041
GARCIA, STACY JOE



Customer Work
Order

