



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH106 844 (PA03997905	Reference no.79785	Status	Approved
--------------------------	----------------------------------	--------------------	--------	----------

Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDFCGL22TV506005	Retail sold on
-----------------------	---------------------------	---	-----------------------	----------------

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root	Approved Actual				Base		Complaint/Cause/Correction
Operation Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
4206819A Home Theatre System - Repair Wiring - External	0	0.5	0.3		1	0.3	Complaint: RECLINER CONTROLS ARE BACKWARDS Cause: The controller for the left recliner is working on the right side. Correction: Removed the mounting screws. Pulled the recliner out. Located control wires and swapped them. Tested function. Placed recliner back in place and secured it to the floor with the mounting screws. KRV – REPAIR ONLY approved.
2300802F Entrance Door - Hinged - Screen Door - Adjust Door	0	0.2	0.2		1	0.2	Complaint: SCREEN DOOR IS HITTING LATCH Cause: The screen door is hitting the latch. Correction: Moved the latch over with a hammer. KRV – REPAIR ONLY approved.
3201014F Door - Interior Sliding - Adjust	0	0.2	0.2		1	0.2	Complaint: BATHROOM SLIDING DOOR IS RUBBING SSTILE Cause: The door is hitting the stile. Correction: Backed the screws out a little to clear the door. KRV – REPAIR ONLY approved.
3100802F Cabinet Door - Adjust	0	0.1	0.1		1	0.1	Complaint: CABINET DOOR NEXT TO SINK IS RUBBING Cause: The top of the doors are rubbing. Correction: Took a hammer and pushed the doors away from each other. KRV – REPAIR ONLY approved.
3200102F Door - Interior Hinged - Adjust	0	0.1	0.1		1	0.1	Complaint: BEDROOM DOOR IS HITTING THE DOORR FRAME Cause: The top of the door is hitting the frame. Correction: Took a hammer and pushed the frame over. KRV – REPAIR ONLY approved.
3201902A Mirror - Repair	0	0.2	0		1	0.2	Complaint: MARKS ON MIRROR IN BEDROOM Cause: Marks on the mirror in bedroom. Correction: Cleaned mirror with glass cleaner. KRV – Cleaning – While in inventory, it is

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

5100302B	Breakaway Switch - Trailer	0	0.2	0.2	1	0.2
	Brakes - Replace					

Pre-Authorization number: PREAUTH106844	1.1
---	-----

Reimbursable in accordance with the
Keystone RV

Policy and Procedure Manual.

Complaint: BRAKE AWAY CABLE IS
DAMAGED

Cause: Damaged section of the breakaway
cable.

Correction: Replaced breakaway cable.
KRV – Labor time approved and adjusted in
accordance with Keystone RV's flat rate
manual.

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount
authorized on the pre-authorization form and return to Keystone RV Company.