

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2665646
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CS2B7TG128597
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSFFAM37
BLANCO CHAPARRODEFRIAS		DEALER RO #	73099-1
11450 PINE TOP		CLAIM START DATE	05/05/2026
Albuquerque, NM 87111		CLAIM END DATE	05/07/2026
USA			
Retail Date of Purchase	05/07/2026	WARRANTY EXPIRATION DATE	05/07/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-99-24-00-001015	Mini-Blind - Interior/Soft Goods/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:02:43 :: Complaint: Kitchen blinds are detached, valance needs to be taken down, blinds need to be reconnected and valance reinstalled Cause: Blinds fell during transport Correction: Remove the upper valance, attached the blinds to the blind hooks, rehung valance, checked operation			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes			
	Authed for a reasonable amount to reattach blinds			

Labor

Line# 2	Operation Code	Operational Description		
	30-91-24-00-004733	Ottoman with Tabletop and Cushion - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:06:57 :: Complaint: Small scratch on wood table in living room Cause: Scratch on table from transport Correction: Used paint marker and filled in the discoloration, then got a rag and wiped off the excess color.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			
	Authed			

Part

Line# 1	Item #	Description		
	USERPART	Paint marker		
	Model #	Serial #	Part tag	
	Sub Qty	Sub Dlr Price	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	Appr Freight	\$0.00
	Notes			
	Considered a shop supply. No mark up applied			

Labor

Line# 3	Operation Code	Operational Description		
	10-9-02-11-000204	Sensing Unit - Frame & Chassis/Levelers, Underbelly/Adjust/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:10:06 :: Complaint: Left side leveling jack had an error code Cause: Jacks had an error code Correction: The unit was just on unlevel ground, was able to adjust up			

and down and it is working properly. Asking for time to test/setup.

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00

Serial# Appr Hrs 0.25 Appr Labor Amt \$47.50

Notes
Authed

Labor

Line# 4

Operation Code

30-101-01-00-001085

Operational Description

Sliding, Pocket Door Latch - Interior/Interior Doors/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:12:23 :: Complaint: Door securing latch pops loose out of door Cause: Screw came loose to secure bathroom door shut Correction: Remove the screw and repositioned the strap. Filled the hole and color match the door.

Model# Dlr Sub Hrs 0.40 Sub Labor Amt \$76.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

Wrong code used

Excessive labor to fill hole, use paint / stain marker and reinstall using a thicker screw. Reduced to a reasonable amount

Part

Line# 1

Item #

USERPART

Description

Filler

Model #

Sub Qty

1.00

Serial #

Sub Dlr Price

\$1.90

Part tag

Sub Freight

\$0.00

Appr Qty

1.00

Appr Dlr Price

\$1.90

Appr Freight

\$0.00

Notes

Considered a shop supply. No mark up applied

Labor

Line# 5

Operation Code

60-140-01-00-001569

Operational Description

Aerator - Plumbing/Bathroom (Lavatory) Sink/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:15:11 :: Complaint: Bathroom aerator is missing Cause: Aerator is missing Correction: Installed new aerator.

Model# Dlr Sub Hrs 0.40 Sub Labor Amt \$76.00

Serial# Appr Hrs 0.05 Appr Labor Amt \$9.50

Notes

Authed for a reasonable amount to install replacement aerator on LAV faucet

Part

Line# 1

Item #

USERPART

Description

Aerotor

Model #

Sub Qty

1.00

Serial #

Sub Dlr Price

\$0.55

Part tag

Sub Freight

\$0.00

Appr Qty

1.00

Appr Dlr Price

\$0.55

Appr Freight

\$0.00

Notes

Submitted

Labor Amt

\$361.00

Parts & Freight

\$6.02

Total

\$367.02

Approved

Labor Amt

\$171.00

Parts & Freight

\$5.30

Total

\$176.30

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.