

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13302B

Date In: 25 APR 26 Author: KOTT  
Promised Date: 25 APR 26 Stock No: 11578  
: Year: 2026  
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER  
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF CLASSIC FW  
: CHICAGO, IL Model: 371RK  
Postal/Zip: 60673-1218 Miles/Hrs: 0  
Phone#(res): 219-534-3167 Exterior Color:  
Phone#(bus): 219-534-3167 Unit Type: FW-FIFTH WHEEL  
Cell Phone: License#:  
Email: NONE Tag#: PU@ST- 4/25@11  
Purchased Date: 24 JAN 26 :  
Delivery Date: 25 APR 26 :  
InService Date: :  
Serial#: 4X4FFLN29T1910906 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - Light on front of W 1021 FORES  
unit is inop the switch is broken on it  
CAUSE: Broken switch on the light  
CORRECTION: Removed lens unscrewed base of light cut  
positive and negative wires obtained new  
fixture ,stripped wires from unit then  
wired light up ,tested it works ,then  
reinstalled onto the unit silicone  
around the fixture and installed lens  
WARR COMPLAINT: WARRANTY REPAIR 2 -THE TRIM ON DINING W 1021 FORES  
/LIVING SLIDE OUT HAS UNFINISHED WOOD  
SHOWING GAPS  
CAUSE: Mfg did not fill the gaps between the  
trim.  
CORRECTION: I used putty to fill all gaps in trim on  
slide room  
WARR COMPLAINT: WARRANTY REPAIR 3 - WHEN PULLING OUT W 1021 FORES  
LOVE SEAT TO MAKE INTO BED THERE ARE  
SHARP STAPLES THAT STAB YOUR FINGER TIPS  
CAUSE: Mfg of sofa did not set the staples  
CORRECTION: Used a hammer and pounded the staples in  
as much as possible so fingertips do not  
get injured when opening up the seat  
WARR COMPLAINT: WARRANTY REPAIR 5 - Table top has a W 1021 FORES  
slight scratch  
CAUSE: Scratch in table top  
CORRECTION: I used very fine wet sand paper to sand  
away the scratch then I polished the

Continued on page 2

Work Order : 13302B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                table top the scratch is no longer
                visable

```

```

*****
Job # Part No      Description           PARTS      Bill to  Qty      Price      Total
*****
WARR0 852661915960 LED OVAL PORCH LIGHT W/  W-1021      1      20.57      20.57

```

```

*****
Job#  Lab Code  Description           LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.49      140.00      68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.01      140.00      1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.46      140.00      64.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.04      140.00      5.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1021      0.50      140.00      70.00

```

```

*****
Job #  Excode      Description           EXTRAS      bill to  Qty      Price      Total
*****
ARR01  SSE          SHOP SUPPLIES - EXTERNAL  W-1021      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      20.57      280.00      0.00      0.00      0.00      300.57
                Totals      20.57      280.00      0.00      0.00      0.00      300.57

```

&k2S  
&k0S