



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64180
Promised Date: 31 MAY 21

CUSTOMER WORK ORDER

WO #: 64180

Customer: 51259 - SHELTON, CHARLES
C. - 270-784-6388

Tag:

Author: BJW

Location: 0520 DELIVERY

Stock #: 10936

Stock Desc: 2021 5W FOREST RIVER

SABRE 36BHQ

Chassis #: 5ZT3SR1BXM6106839

Serial #: 5ZT3SR1BXM6106839

Mileage:

Licence:

Invoice #:

Date In: 11 MAY 21

Promised: 31 MAY 21

Date Sched:

Completed: 21 MAY 21

Warr. Date: 24 APR 21

Job #1 - Internal

COMPLAINT: INSTALL 4 TV AND BRACKET. LABOR
PREBILLED ALONG WITH 4 MOUNTS

CAUSE: INSTALL 4 TV AND BRACKETS.

CORRECTION: Moved unit back into shop from wash bay area. Removed main TV in living room from mount. Installed new 40" smart tv in living room. Connected to antenna and ran channel scan. Assembled legs on 24" Tv for upper bunk.. Placed TV on mattress on bunk. Installed backer board in front storage compartment for mounting 32 in. TV. Installed swing out bracket on backer board. Mounted TV on bracket. TV will not swing out far enough to see TV from under awning. Removed TV and bracket from backer board. Changed TV bracket to a double swing out mount. Mounted bracket on backer board. mounted TV on new bracket. Made up coax cable to connect to antenna. Checked operation of TV and antenna. Picked up channels inside shop. Located and mounted TV wall bracket in bunkroom. Installed TV on wall bracket. Made up coax cable to connect to antenna. Checked operation of TV and antenna. Found channels. Located and mounted bracket on wall over dresser in front bedroom. Installed TV on wall bracket. Made up coax cable to connect to antenna. Checked operation of Tv and antenna. Found channels. Hauled off all trash from TV's. Moved unit back to wash bay area.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
24-0167	TV5-002H MOR/RVDE	2.00	N/C	N/C
24-0121	TV Mount; Wall Mo	-2.00	N/C	N/C
24-0146	TV1-025H SWIVEL/TI	-2.00	N/C	N/C
24-0146	TV1-025H SWIVEL/TI	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: IMNSTALL PRE BILLED COMPANION IN TRUCK

CORRECTION: INSTALLED COMPANION HITCH INTO TRUCK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C



Customer #: 51259
SHELTON, CHARLES C.

Subtotal for Job #2: 0.00

Job #3 - Internal
 PREBILLED WALK THRU

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	EF	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CAMERA NOT WORKING WHILE IN THE TRUCK

CAUSE: CAMERA NOT WORKING WHILE IN TRUCK.

CORRECTION: Removed factory back-up camera from unit. Spliced in new Furrion back-up camera. Mounted camera over original holes. Checked operation with monitor. Monitor and camera working together. Sealed around camera with clear silicone.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	65.00

Parts Part #	Description	Qty	Price	Total
732556	FURRIION 5" REAR CA	1.00	286.35	286.35

Subtotal for Job #4: 351.35

Parts Total: 286.35
 Labour Total: 65.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 351.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Aug 2021

Customer #: 51259
 SHELTON, CHARLES C.

