

Nexus Dealer

AUTHORIZATION #: 17690

Phone: Phone:

Nexus RV Serial Number: 18780

b.parrott@myersrv.com;Rhianna.s@myersrv.com

Work/Repair Order: 73271

Date of Purchase:

Service In Date: 04/27/2026

Year: 2026 **Make:** Ghost **Model:** 38DS

Service End Date:

Mileage: 1,679.00

Bill Ref #: 17690

VIN: 1HTEUMML1TS217297

Date: 05/07/2026 **Created By:** Christy

Estimate Prepared For Customer:

Status: Authorization Approved

Estimate Prepared For Service Location: 98001

Myers RV Center
12024 Central Ave SE

Albuquerque NM, 87123

Item Code	Description	Complaint	Cause	Correction	Rate	Qty	Amt	Nexus Hrs	Nexus Amt
1 2025A	ACCESS DOORS-BUS STYLE - GAS STRUT-R&R	Genset door is missing strut	Strut is missing	Replace strut	195.00	0.20	39.00	0.20	39.00
2 4260B	VALANCE R&I	Shade and valance detached in living room and behind bed	Fasteners failed	Reattach shade/valance	195.00	0.50	97.50	0.50	97.50
3 7062B	CEILING FAN-R&RI	E1 on Dometic ceiling exhaust fan	Missing fuse and holder	Order and replace holder/fuse - I had found code 7180A for this, but it would not pop up here. Chose next best labor code I could find.	195.00	0.30	58.50	0.30	58.50
4 7081A	12V CIRCUIT BREAKERS-R&R (AUTO RESET)	Solar is not connecting to batteries	Missing cover plate and has underrated fuse	Order plate and replace fuses, tested and calibrated. I had found code 2057A in the flat rate manual for this, but it will not populate here. Chose next best labor code.	195.00	0.50	97.50	0.50	97.50

Nexus Dealer

Phone: Phone:

b.parrott@myersrv.com;Rhianna.s@myersrv.com

Date of Purchase:

Year: 2026 Make: Ghost Model: 38DS

VIN: 1HTEUMML1TS217297

AUTHORIZATION #: 17690

Nexus RV Serial Number: 18780

Work/Repair Order: 73271

Service In Date: 04/27/2026

Service End Date:

Mileage: 1,679.00

Bill Ref #: 17690

Bill Ref # Date:

Date: 05/07/2026 Created By: Christy

Estimate Prepared For Customer:

Status: Authorization Approved

Estimate Prepared For Service Location: 98001

Myers RV Center
12024 Central Ave SE

Albuquerque NM, 87123

Item Code	Description	Complaint	Cause	Correction	Rate	Qty	Amt	Nexus Hrs	Nexus Amt
5 8330A	WASHER/DRYER R&R	NO water to washer, E1/F8	NO water flow. We are not sure if there is a valve issue on the coach side or the issue is within the washer. We have to pull the washer to access the water lines and valve. Need to verify the water flow to the washer or if there is an issue at shut off valve.	I found 8330B in the flat rate manual, but it will not populate here to R/I the washer. Found next best code. Asking for time to pull washer and diag concern.	195.00	3.00	585.00	1.50	292.50
6 3434A	WALL PANEL R&R	Monitor panel is protruding from wall	Improper fasteners used causing stripped out hole	Replace wall panel	195.00	5.00	975.00	2.00	390.00
7 8300B	AC " ROOF MOUNT DUOTHERM / DOMETIC-AIR CONDITION	Front AC ceiling assembly is falling off of corner	Found that it was not secure	Resecured	195.00	0.50	97.50	0.50	97.50
8 2372J	ACCESS DOORS-BUS STYLE - LOCK " STRIKER (PER DOO	Compartment door next to entry door will not stay shut	Striker misalignment	Realign and test	195.00	0.30	58.50	0.30	58.50
9 3232A	LOCK HOLLOW CORE DOOR-SLIDING/P OCKET R&R	Magnet misaligned for bathroom pocket door	Wrong location	Relocate and covered old hole and test	195.00	0.30	58.50	0.30	58.50

Nexus Dealer

Phone: Phone:

b.parrott@myersrv.com;Rhianna.s@myersrv.com

Date of Purchase:

Year: 2026 Make: Ghost Model: 38DS

VIN: 1HTEUMML1TS217297

AUTHORIZATION #: 17690

Nexus RV Serial Number: 18780

Work/Repair Order: 73271

Service In Date: 04/27/2026

Service End Date:

Mileage: 1,679.00

Bill Ref #: 17690

Bill Ref # Date:

Date: 05/07/2026 Created By: Christy

Estimate Prepared For Customer:

Status: Authorization Approved

Estimate Prepared For Service Location: 98001

Myers RV Center
12024 Central Ave SE

Albuquerque NM, 87123

Item Code	Description	Complaint	Cause	Correction	Rate	Qty	Amt	Nexus Hrs	Nexus Amt
10 2210B	MOLDINGS Exterior-STEP-ENTRY DOOR-ELECTRIC-R&I	Screws are not the same color at entryway interior steps	Wrong hardware was used	Replace hardware. Had found 2209L in the flat rate manual, but it would not populate here. Chose a close code.	195.00	0.30	58.50	0.30	58.50
11 1466A	DASH A/C-HEATER ASSEMBLYCONT ROL PANEL FACE PLATE-	MPPT is missing the cover plate	Cover plate is missing	Order and replace cover plate	195.00	0.50	97.50	0.50	97.50
12 3432B	WALL-NON-LAMINATED PANEL WOOD GRAIN R&I	Wall in living room is detaching at floor causing waves	The wall is too tall	Pull wall panel, r/i mirror, trimmed wall panel and reinstalled	195.00	2.00	390.00	1.00	195.00
13 2117C	CAPS CORNER CAPS-ABS PLASTIC-FRONT CAP 2-PIECE CLA	Stress crack on front cap above the driver door	Sublet for repair	Sublet for repair, still need to get an estimate, but wanted to get the line in. Amount is not yet known.	195.00	0.00	0.00	0.00	0.00
14 3284A	VINYL FLOORING &R	Just noting at this time, dents in floor from tools?	Dents in the flooring near dinette and couch in living room.	Just noting at this time.	195.00	0.00	0.00	0.00	0.00

Requested	Authorized
\$2,613.00	\$1,540.50

Comments:

Nexus Subtotal: \$1,540.50
Sales Tax: \$0.00
Total: \$1,540.50