

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13228

Date In: 17 FEB 26 Author: MGRAY  
Promised Date: 31 DEC 26 Stock No: 11227  
: Year: 2025  
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN  
Address: 11333 COUNTY RD 2 Brand: IMAGINE XLS  
: MIDDLEBURY, IN Model: 23LDE  
Postal/Zip: 46540 Miles/Hrs: 0  
Phone#(res): 888-825-2820 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: db 2/23  
Purchased Date: 16 APR 25 :  
Delivery Date: 08 MAY 25 :  
InService Date: :  
Serial#: 573TE282XS3440902 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: BEARING REPACK - CMR REQUESTS THAT THEY E 15106 FEUER  
ARE JUST DONE AS THEY ARE TAKING ON A  
LONG TRIP.  
CAUSE: repack all 4 bearings  
CORRECTION: removal of tires and hubs from axles i  
also inspected bearings ok repack  
bearings with new grease and hub seals  
installed all 4 hubs and torqued tires  
to spec  
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF I PD GOODW  
REPAIR IS NEEDED.  
CAUSE: roof inspection  
CORRECTION: roof inspection was done all vents and  
sealants are ok  
WARR COMPLAINT: WARRANTY REPAIR 1 - FENDER SKIRTS HAVE W 1020 GRAND  
SOME CRACKING. LOOK LIKE THEY HAVE BEEN  
tightened down to tight.  
CAUSE: pics and measurements taken on door side  
fender skirt is cracked  
CORRECTION: will need a new fender skirt.....  
request: 1.0  
2 COMPLAINT: THE NEWLY INSTALLED SHADE HAS CAPS ON W 1020 GRAND  
THE BOTTOM SECTION TO KEEP METALL INSIDE  
AND NONE OF THE OTEHR SHADES DO, ARE  
THEY SUPPOSED TO BE CAPPED OLIKE THAT?  
AND IF SO CAN WE GET THE CAPS TO REPLACE  
THEM?  
CAUSE: inspection of all shades the newly shade

Continued on page 2

