



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27037



WO #: 27037

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11223

Stock Desc: 2026 O FOREST RIVER CEDAR

CREEK 29RL

Model: 29RL

Serial #: 4X4FCRE23TS235365

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN 20-1983  
REAR WINDOWS

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN 20-1983  
THIS IS DOOR SIDE REAR WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN 20-1983  
THIS IS REAR WINDOW ON DS SLIDE OUT

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN 20-1983  
FRONT WINDOW ON DS SLIDE

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN 20-1983  
DS FRONT CAP WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: TECH SERVICE BULLETIN  
NDS REAR WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING,APPLY FOAM TAPE AND  
INSTALL NEW WINDOW  
LABOR 2.0

**Subtotal for Job #6: 0.00**

Customer Work Order

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>0.00</b>

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 12 May 2026

