

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12452

Date In: 25 JUL 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11043
: Year: 2024
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: FLAGSTAFF MICRO-LITE
: CHICAGO, IL Model: 21DS
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: not paid in full- WS C
Purchased Date: 01 FEB 25 :
Delivery Date: 05 MAY 25 :
InService Date: :
Serial#: 4X4TFLW27RD458074 :

Job # Description JOB INFORMATION Type Bill To

SS COMPLAINT: SEASONAL STORAGE E 17609 WOLF
CAUSE: NEED STORE
CORRECTION: STORED
WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 17609 WOLF
CONTAINED - TOWABLE
CAUSE: Unit needed winterize
CORRECTION: Unit winterized 10/1/25
SUM COMPLAINT: SUMMERIZE CAMPER AND DEWINTERIZE E 17609 WOLF
CAUSE: Unit needed winterize summerize unit
CORRECTION: Unit winterized 10/1/25 unit summerized.
WARR COMPLAINT: WARRANTY REPAIR 1 - THE BATHROOM FAUCET W 1021 FORES
LEAKS SOMEWHERE BELOW THE SINK. WATER
POOLS ON THE FLOOR IN THE BATHROOM.
UNDER THE SINK THEN RUNS ON TO FLOOR.
CMR BELIEVES THAT THE LEAK IS COMING
FROM THE COLD WATER LINE.
CAUSE: Customer stated bathroom sund has a leak
CORRECTION: Did a water test on it left over night
did not see a leak did a aire pressure
test on it and did not find a leak
request: .5 DECLINED
WARR COMPLAINT: WARRANTY REPAIR 2 - AS YOU ARE SITTING W 1021 FORES
ON THE SOFA, THE LEFT RECLINER MECHANISM
DOES NOT WORK. LEVER IS MOVING, BUT DOES
NOT ENGAE THE FOOT REST
CAUSE: test recliner on left side of sofa.
customer says it won't open the door
rest when the release is pulled.

Continued on page 2

Work Order : 12452

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: tested multiple times and it work.
           couldn't duplicate problem.  REQUEST .5
           DECLINED
WARR    COMPLAINT:  WARRANTY REPAIR 3 - THE WINDOW TO THE   W    1021  FORES
           RIGHT OF THE SOFA WHEN SITTING ON IT HAS
           A SCREEN THAT DOES NOT FIT SNUGGLY.
CAUSE:   check window to the right of sofa for
           gaps in the screen. The inner part of
           the frame is bent on the left side where
           the seam is. May need to replace window.
CORRECTION: Went and got a special pair of plyers to
           bend the metal frame inside straight for
           a better seal with the screen. Screen
           now fitting properly  request: 1.4
WARR    COMPLAINT:  WARRANTY REPAIR 4 - STRAP TO PULL OUT   W    1021  FORES
           SOFA TORE LOOSE.
CAUSE:   sofa strap ripped open the fabric it was
           sewen to. need to repair of replace
           sofa.
CORRECTION: ... need direction from manu on how to
           repair, or if need replacement.  DENIED
    
```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WS     071247312003 -50 ANTIFREEZE/ 1 GALLON E-17609   0     9.62    0.00
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
WS W495 WINTERIZE RV (WATER SY TD E-17609 0.00 130.00 0.00
WS W495 WINTERIZE RV (WATER SY JT E-17609 0.70 130.00 91.00
SUM Z990 SUMMERIZE JT E-17609 0.00 130.00 0.00
SUM Z990 SUMMERIZE TD E-17609 0.50 130.00 65.00
ARR01 Z992 MISC LABOUR CODE (WARR JT W-1021 0.50 140.00 70.00
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1021 0.50 140.00 70.00
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1021 0.00 140.00 0.00
ARR04 Z992 MISC LABOUR CODE (WARR TD W-1021 0.00 140.00 0.00
ARR04 Z992 MISC LABOUR CODE (WARR TD W-1021 0.21 140.00 29.40
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1021 0.36 140.00 50.40
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1021 0.04 140.00 5.60
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1021 0.50 140.00 70.00
    
```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
SS SS SEASONAL STORAGE E-17609 1.00 207.00 207.00
SS SSE SHOP SUPPLIES - EXTERNAL E-17609 1.00 11.70 11.70
SS J-ADJ QUOTE ADJUSTMENT E-17609 1.00 -11.70 -11.70
    
```

Continued on page 3

Work Order : 12452

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
  WS   J-ADJ     QUOTE ADJUSTMENT      E-17609   1.00   14.00   14.00
  SUM   J-ADJ     QUOTE ADJUSTMENT      E-17609   1.00  -10.00  -10.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
E   17609          0.00    156.00     0.00    211.00     20.20    387.20
W   1021          0.00    295.40     0.00     0.00       0.00    295.40

      Totals          0.00    451.40     0.00    211.00     20.20    682.60
*****
```

&k2S
&k0S