



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27086 SMITH, EARL

Estimate: 27086 (Appointment Date: 29 APR 2026 - Time: 01:30pm)

Customer: 80675 - SMITH, EARL
Address: 1396 WEAVER BRANCH ROAD
PINEY FLATS, TN
37686

Home Phone: (423) 956-1590

Work Phone:

Author: CHL

Location: IH

Invoice #: 423208

Stock #: 11173

Stock Desc: (11173) 2020 FOREST RIVER
FORESTER 2861DS

Model: 2861DS

Serial #: 1FDXE4FS4KDC49165

Chassis #: 1FDXE4FS4KDC49165

Mileage: 6000

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 08 AUG 25

Date In: 29 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 29 APR 26

Warr. Date: 08 AUG 25

Job #1 - External

COMPLAINT: dewin

CORRECTION: DEWINTERIZED JCS

Parts

Part #	Description	Qty	Price	Total
VLPA01-1136	CARBON BLOCK FILTER, EXTERIOR CARTRIDGE REPLACEMENT, 10IN, 8 EQUIVALENT	0	35.09	0.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: CS THAT THERE IS 2 DRAWERS THAT WONT STAY CLOSED (ASK FOR LOCATION)

CORRECTION: TECH FLIPPED OUT LATCHES AND TESTED DRAWERS THEY ARE WORKING

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CS THAT THERE IS A RUBBER SEAL COMING LOOSE ON THE SLIDE CHECK AND
ADVISE (ASK FOR LOCATION)

CORRECTION: TECH FOUND SEAL WORKING AS DESIGNED SOMETIMES THE RUBBER GETS
STUCK IN PLACE



Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CS THAT THERE IS A SIDE CAMERA THAT IS INOP CHECK AND ADVISE

CORRECTION: NEED TO REACH OUT TO FR FOR PART INFO AND CALL CUSTOMER WITH QUOTE

Subtotal for Job #4: 0.00

Job #5 - External

MAIN ENTRY DOOR IS HARD TO SHUT CHECK AND ADVISE

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 29 Apr 2026

