

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2677441
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC7TG815523
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16BHX-452
		DEALER RO #	72853-1
		CLAIM START DATE	05/15/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-100-01-00-001050	Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-15 12:43:34 :: Complaint: Found refer to be loose Cause: Refer was not secured properly. Screw was broken. The refer screw had broken the style. Correction: Remove refer. In order to install a new style the furnace needs to be taken out and the gas line disconnected, along with any electrical wires. The fuse box also has to be unscrewed and wires have to be taken off in order to place a new style in. The wood around the style needs to be taken apart to add a new style and then screwed back into the factory location. The furnace will need to be reinstalled in factory location, wires need to be reconnected, fuse panel reinstalled and wires reconnected. Checked all for proper operation. Refer has to be wires and screwed back in factory location and test for proper operation, Style is 2 x 20 long.			
Model#	Dlr Sub Hrs	3.50	Sub Labor Amt	\$665.00
Serial#	Appr Hrs	3.50	Appr Labor Amt	\$665.00
	Notes			
	Authed			

Submitted	Labor Amt	\$665.00	Approved	Labor Amt	\$665.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$665.00		Total	\$665.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.