



Claim CLAIM102075 (C3945188)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Changed		Date of Purchase
								Labor rate	warranty rate	
CLAIM102075 (C3945188)	39285	9/8/2025	4/30/2026	4YDTATL26T8920355	PA03985946	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR 1/1/1970

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Part Markup	Appr total	Sub Freight	Sublet	Status	
30	768121	Trim - T-Mold - 11/16" - Double Lip - Cortona Gilden - 600 Ft/RI	5	0	0.48	30.00	3.12	25.32	25.32	0.00	Approved
	211115	Warranty Shop Supply - Paint and Paint Supplies	1	0	5.00	30.00	6.50	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
3102614B	Dinette Seat Base - Stile - Replace		1	1	165	0	1	0.5	Approved
	Complaint Dealer states trim piece on backrest of dinette is missing.								
	Cause Missing trim on dinette.								
	Correction 3'-4' is the length that needs to be replace. Replace trim.								

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
2101308A	Metal Lower Wrap		0.5	0.5	82.5	0	1	0.5	Approved
	Complaint Dealer states driver damage: scratch on drivers side towards front.								
	Cause Scratch from driver.								
	Correction Cleaned, taped and painted scratch with paint marker. Dealership recommends new sheet metal for proper fix - if Keystone would like dealership to do this, please let us know and we will enter a new PA for that.								
	KRV- Please Touch area up.								

Submitted parts & subLet	9.62	Approved parts & subLet	9.62
Submitted labor & subLet	247.50	Approved labor & subLet	247.50
Submitted freight	25.32	Approved freight	25.32
Total Submitted	282.44	Total approved	282.44