

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497		CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2660851
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TPUS26SP104401
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	420 / 420
		ITEM #	PUT403LFT
		DEALER RO #	12285
		CLAIM START DATE	04/30/2026
		CLAIM END DATE	05/06/2026
Labor rate:	\$140.00		
OWNER INFORMATION			
KIMBERLIE STANDIFORD			
4607 Bannoch Drive			
Racine, WI 53402			
USA			
Retail Date of Purchase	05/24/2025	WARRANTY EXPIRATION DATE	05/24/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-56-19-00-000600	Slide Out T-Molding, each - Exterior/Slide Out System-Seals, Exterior Room/ Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-04-30 17:24:00 :: Complaint: Customer states the back living room slideout needs to be caulked. Cause: On off door side, middle exterior slide, the t-molding on left side needed some silicone. Correction: cleaned the area on exterior t-molding, applied silicone and other areas needed, the slide is now sealed properly. Previous PA 2363129 expired.			
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$98.00
Serial#	Appr Hrs	0.70	Appr Labor Amt	\$98.00
	Notes			
	per expired claim 2363129			

Part

Line# 1	Item #	Description	
	USERPART	shop supplies - silicone	
	Model #	Serial #	Part tag
	Sub Qty	1.00	Sub Dlr Price \$4.90
	Appr Qty	1.00	Sub Freight \$0.00
		Appr Dlr Price	Appr Freight \$0.00

Notes

Labor

Line# 2	Operation Code	Operational Description			
	30-99-01-00-001018	Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : greeneway@dealer-advisors.com, 2026-04-30 17:24:45 :: Complaint: Customer states left front kitchen blind is short. Cause: Blind is short. Correction: Replace shade. Previous PA expired				
	Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$56.00
	Serial#	Appr Hrs	0.40	Appr Labor Amt	\$56.00
	Notes				
	per expired claim 2363129				
	only vcb .20				

Part

Line# 1	Item #	Description	
	F100445363	SHADE, ROLLER 27 X 38 (24 X 36 WINDOW) Bamboo Black Fabric/Keyhole PC Alum Hembar w/Auto Stop 2024	
	Model #	Serial #	Part tag

Sub Qty	1.00	Sub Dlr Price	\$47.09	Sub Freight	\$6.21
Appr Qty	1.00	Appr Dlr Price	\$47.09	Appr Freight	\$6.21

Notes

Labor

Line# 3

Operation Code
30-99-01-11-004367
Operational Description
Motorized Roller Shade - complete - Interior/Soft Goods/Replace/Electrical
Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-04-30 17:25:24 :: Complaint: Customer states top living room blind over couch has two holes in it. Cause: This is a motorized shade, has holes in it. Correction: Replace motorized shade. Previous PA expired

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$70.00

Notes

per expired claim 2363129
only vcb .40

Part

Line# 1

Item #	Description
F100490839	SHADE, MOTORIZED ROLLER, 42" X 14" BLACK
Model #	Serial #
Sub Qty	1.00
Sub Dlr Price	\$111.01
Sub Freight	\$6.21
Appr Qty	1.00
Appr Dlr Price	\$111.00
Appr Freight	\$6.21

Notes

Labor

Line# 4

Operation Code
30-99-01-00-001018
Operational Description
Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-04-30 17:26:13 :: Complaint: Customer states small blind by recliner had a hole in it. Cause: Hole in shade. Correction: replace shade. Previous PA expired

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$56.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$56.00

Notes

per expired claim 2363129
only vcb .20

Part

Line# 1

Item #	Description
F100783236	ROLLER SHADE, 20 X 42 BLACK VINYL, BLACK BACKING/PC ALUM HEMBAR W/AUTO STOP
Model #	Serial #
Sub Qty	1.00
Sub Dlr Price	\$44.29
Sub Freight	\$42.69
Appr Qty	1.00
Appr Dlr Price	\$44.29
Appr Freight	\$42.69

Notes

Labor

Line# 5

Operation Code
20-43-19-00-001109
Operational Description
Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code
Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2026-04-30 17:26:46 :: Complaint: The customer states the AC is not draining correct, will drip down over the patio. Cause: The gutter track, the seam was leaking above patio. Correction: Used non-leveling black lap sealant to seal in gutter and the seam below. Previous PA expired

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$70.00

Notes

per expired claim 2363129

Part

Line# 1	Item #	Description			
	USERPART	shop supplies - lap sealant			
	Model #	Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$3.50	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$3.50	Appr Freight \$0.00
	Notes				

Submitted			Approved		
	Labor Amt	\$350.00		Labor Amt	\$350.00
	Parts & Freight	\$265.90		Parts & Freight	\$265.89
	Total	\$615.90		Total	\$615.89

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.