



Warranty Claim Form

Date: 5/18/2026

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TM2726TBB05490

Momentum 21G

Retail Purchase Date: 4/22/2026

Work Started: 4/16/2026

Work Completed: 4/21/2026

Claim Status: Paid

Dealer Work Order #: 13317B

Unit Offline Date: 3/10/2026

Claim #: 986600

Labor: \$28.00

Parts: \$1.40

Shipping: \$0.00

Total: \$29.40

Notes: RJ 04/27/2026 *please hold parts until 30 days after the claim is paid.

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 550032 Sealing - Attachments

Fault Code: Improper Installation/Build

Problem: There is a cap where the furnace plate meets the wall on the outside.

Hours: .2

Cause: The furnace vent has a gap that could let water into the furnace.

Amount: 28.00

Remedy: Took silicone and ran it around the top.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.40