

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2679296
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVRB0TB942144
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT26DBS
		DEALER RO #	73040-1
		CLAIM START DATE	05/18/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-101-01-00-001078	Sliding, Pocket Door - Interior/Interior Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-18 13:59:57 :: Complaint: Bedroom sliding door is damaged Cause: This is noted on DAF. Sliding door is scrapped on edges towards the front of the unit near entrance. Correction: Door needs to be removed from the slider rail and unscrewed. To remove the door the slide for the door is attached and has to be unscrewed from the roof of the unit. The new door has to be attached to the sliding rail and then the rail has to be rescrewed to the roof and the door must be tested to ensure it is working. New door has to be ordered.			
Model#	Dlr Sub Hrs	0.85	Sub Labor Amt	\$161.50
Serial#	Appr Hrs	0.85	Appr Labor Amt	\$161.50
	Notes			
	Authed as requested. Hope the screws for this are only attached to the ceiling.			

Submitted	Labor Amt	\$161.50	Approved	Labor Amt	\$161.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$161.50		Total	\$161.50

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.