



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79798
Promised Date:
07 MAY 26

CUSTOMER WORK ORDER

WO #: 79798

Customer: 55823 - BLAKE, ZACHARY -
812-217-3361

Tag:

Author: BH

Location: 0518 CHECK PREAUTH

Stock #: 11604

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT 261BHS

Chassis #: 5ZT2CARB9SU046253

Serial #: 5ZT2CARB9SU046253

Mileage:

Licence:

Invoice #:

Date In: 04 MAY 26

Promised: 07 MAY 26

Date Sched:

Completed: 18 MAY 26

Warr. Date: 07 MAY 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: New final

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Installed a new battery. Running lights and tail lights work properly brakes and Emergency Brakes work properly. Front cap lights need to be seated I. The track. And door side has a black line through the light. Exterior inspection entry door needs adjusted it is hitting on the striker. I got it fixed and door works properly now. Exterior looks good. Roof inspection found a few voids that I sealed with dicor self-leveling roof good now. Put water in fresh tank and ran the water pump to flush out the lines water pump works properly then hooked to city water and flushed out all the lines water heater works properly on both. Stove works properly microwave works properly both refrigerators work properly furnace works properly ac works properly. Replaced the shower hose. Fixed bedroom door fixed dinette seats trim. Tv antenna works properly radio works properly. Awning fabric and hardware looks and works properly Awning lights work properly. Remotes in shelf by radio. All lights and windows and blinds work properly ran a new ground wire for water pump. Fixed door side cap light track and the cap light on off door side. Did my lp drop test on outside port with stove and furnace running made a small adjustment to regulator system works properly now. Fixed the lp regulator it was not on top of the tank hold down. Fixed the pannel trim tape the was loose by the dinette table. Drained black tank and gray tank and left 1/3 in the fresh tank for demonstration

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
80-01-2160	"ZIP" BREAKAWAY CABLE 6'	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #ICSH - Internal

COMPLAINT: INSTALL CUSTOMER SUPPLIED HITCHWORK

CAUSE: Installed customer supplied hitch

CORRECTION: Inspection of customer hitch found that it was missing parts and we didn't have the parts so sales sold him a new hitch

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



Customer #: 55823
BLAKE, ZACHARY

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ICSH:

0.00

Job #1 - Warranty

COMPLAINT: LIGHT ABOVE THE KITCHEN SINK IS FLICKERING WHEN PUMP IS TURNED ON

CAUSE: Light above sink flickers when water pump running

CORRECTION: So i ran a ground wire from water pump to the ground bus bar and ran my water pump and light doesn't flicker anymore and works properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	91.65
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	64.35

Subtotal for Job #1:

156.00

Job #2 - Internal

COMPLAINT: SHOWER HOSE HAS A KINK AND NEEDS REPLACED

CAUSE: Shower hose is kinked

CORRECTION: Shower hose was kinked bad and couldn't get water through it. So I replaced it with a new one. And it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
72-3359	PW 60" VINYL SHOWER HOSE & BRACKET ONLY	1.00	N/C	N/C

Subtotal for Job #2:

0.00

Job #3 - Warranty

COMPLAINT: THE BATHROOM DOOR IS NOT CLOSING ALL THE WAY

CAUSE: Bathroom door won't stay shut

CORRECTION: On inspection of the bathroom door the striker was too low and the door would not latch. So I took the striker plate off and moved the hole upward then put the striker plate back on and door shuts properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	39.00

Subtotal for Job #3:

39.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work

CORRECTION: Installed hitch brakets on camper. And put the head in the receiver. And hooked up everything and tightened down everything. Good to go

W/O: 79798
 Promised Date: 07 MAY 26



Customer #: 55823
 BLAKE, ZACHARY



W/O: 79798
Promised Date: 07 MAY 26

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E2: 0.00

Parts Total: 0.00
Labour Total: 195.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 195.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 May 2026

Customer #: 55823
BLAKE, ZACHARY