

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 12285

Date In:	28 JUN 25	Author:	DLUCAS
Promised Date:	23 APR 26	Stock No:	11299
:	:	Year:	2025
Customer Name:	14589 - STANDIFORD, KI	Manufacturer:	FOREST RIVER
Address:	4607 BANNOCH DRIVE	Brand:	PUMA DESTINATION
:	RACINE, WI	Model:	403LFT
Postal/Zip:	53402	Miles/Hrs:	0
Phone#(res):	262-752-8808	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	TSTANDIFORD@YAHOO.COM	Tag#:	DB: 7/10 - swp4/30
Purchased Date:	26 APR 25	:	:
Delivery Date:	09 JUN 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS26SP104401	:	:

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
SC      CUSTOMER REQUESTS SERVICE CALL TO 872 7TH AVE           E    14589  STAND
        HANCOCK
1       COMPLAINT:  CUSTOMER STATES BACK LIVING ROOM           W    1021  FORES
        SLIDEOUT NEEDS TO BE CAULKED
        CAUSE:      on off door side middle exterior slide
        the t molding on left side needed some
        silicone pics taken
        CORRECTION: cleaned the area on exterior t molding
        applied silicone and other areas needed
        the slide is sealed REQ .70 HRS WARR
        AUTH: .70
2       COMPLAINT:  CUSTOMER STATES LEFT FRONT KITCHEN BLIND W   1021  FORES
        IS SHORT
        CAUSE:      pics and measurements taken need a new
        shade
        CORRECTION: install the new shade in kitchen
        adjustments made the shade is now
        working
3       COMPLAINT:  CUSTOMER STATES TOP LIVING ROOM BLIND       W    1021  FORES
        OVER COUCH DS HAS TWO HOLES IN IT
        CAUSE:      this is a motorized shade pics and
        measurements taken
        CORRECTION: above the couch i had removed and
        installed the shade and wired the 12
        volt connections i also had to set the
        stop on shade and tested after
        adjustments now working
4       COMPLAINT:  CUSTOMER STATES SMALL BLIND BY RECLINER    W    1021  FORES
  
```

Continued on page 2

Work Order : 12285

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                HAS A HOLE IN IT
CAUSE:    pics and measurements taken will need
          the correct shade the one they sent us
          is black on black and the one the
          customer has is a white backer and the
          black doesn't look the same
CORRECTION: Will need a new shade... will need
            correct shade .....
5 COMPLAINT: CUSTOMER STATES AC IS NOT DRAINING           W      1021   FORES
          CORRECTLY STILL AFTER REPAIRS STILL HAS
          A PINHOLE LEAK SEEMS LIKE BEHIND AWNING
CAUSE:    pics taken the gutter track the seam was
          leaking above patio
CORRECTION: used non leveling black lap sealant to
            seal in gutter and the seam below
6 COMPLAINT: MORRYDE STEP RECALL 25V245                   W      1021   FORES
CAUSE:    pics taken
CORRECTION: pics taken
7 COMPLAINT: BEDROOM DOOR IS DIFFICULT TO SHUT SEEMS W      1021   FORES
          LIKE ITS CATCHING, SEEMS TO BE GETTING
          WORSE
CAUSE:    pics taken what i found was the door
          latch to close to striker plate due to
          loose hinges
CORRECTION: tighten all the screws in all three
            hinges the bedroom door is now closing
            smoothly

```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
2      82205363  SHADE, ROLLER 27 X 38 BAMB W-1021         1     47.09   47.09
6      82204078  RECALL KIT MORRYDE STEPS  W-1021         0      0.00    0.00
3      822090839  SHAD, MOTORIZED ROLLER, 42 W-1021         1    111.01  111.01
4      8220490839  SHADE, ROLLER 20 X 42 BAMB W-1021         1    111.01  111.01

```

```

*****
Job# Lab Code  Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
1 WARR      MANUFACTURER WARRANTY JS   W-1021     0.70  140.00  98.00
2 WARR      MANUFACTURER WARRANTY JS   W-1021     0.10  140.00  14.00
3 WARR      MANUFACTURER WARRANTY JS   W-1021     0.14  140.00  19.60
4 WARR      MANUFACTURER WARRANTY JS   W-1021     0.24  140.00  33.60
5 WARR      MANUFACTURER WARRANTY JS   W-1021     0.80  140.00  112.00
2 WARR      MANUFACTURER WARRANTY JS   W-1021     0.50  140.00  70.00
3 WARR      MANUFACTURER WARRANTY JS   W-1021     0.50  140.00  70.00
4 WARR      MANUFACTURER WARRANTY JS   W-1021     0.50  140.00  70.00
6 WARR      MANUFACTURER WARRANTY JS   W-1021     0.50  140.00  70.00
7 WARR      MANUFACTURER WARRANTY JS   W-1021     0.50  140.00  70.00

```

Continued on page 3

Work Order : 12285

```
*****
Job #  Excode   Description  EXTRAS      bill to     Qty    Price    Total
*****
SC  SSE      SHOP SUPPLIES - EXTERNAL  E-14589   1.00    0.00     0.00
SC  SC       SERVICE CALL                E-14589   0.00    3.75     0.00
  3  FRT      FREIGHT FOR ALL SHADES JOB W-1021  1.00    18.64    18.64
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
W   1021          269.11   627.20    0.00     18.64     0.00    914.95
      Totals      269.11   627.20    0.00     18.64     0.00    914.95
*****
```

&k2S
&k0S