



1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16T8920549
1 Mi In / 2 Mi Out
In Service Date:
01/01/2017
Stock #: KS26-36

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STAES THE FURNACE FAN SOUNDS LIKE IT IS RUBBING ON SOMETHING WHEN OPERATING	Warranty Pay	\$214.50
----	---------------	--	--------------	----------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Misadjusted blower wheel in housing. 1.30hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$214.50

Labor Cost: \$37.90

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.94	1	1	\$165.00	\$31.00
shurterc	-	0	0.3	0.3	\$49.50	\$6.90
matthewl	-	0	0	0	\$0.00	\$0.00

1. Removed the exhaust, then removed the interior cover over the furnace. After disconnecting the LP line from furnace, tried to pull furnace out. The wires to furnace were tight before the furnace would come out, so removed the bunk cover that was adjacent to the furnace and removed the screw holding the wires to the bunk frame. Once removed, was able to pull furnace out the rest of the way. Took the blower cover off and checked the smaller blower wheel, which looked good and was not rubbing. Removed small blower wheel and removed the other side of the blower cover to access the larger blower wheel. Could see that the fan blades had been rubbing against the opening that it sits in. Adjusted the blower wheel, then partially reinstalled cover to test that there was no longer any rubbing. Once confirmed, removed cover and put the small blower wheel back on, reinstalled the cover pieces, and tested again. Still no rubbing, so proceeded to put the furnace back in and reconnected LP line, put the furnace cover on, and put the exhaust back in. Tested a final time without issue. Sealed the exhaust.

Total Labor Sale
\$214.50

Total Labor Cost
\$37.90

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG16 T8920549	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

B. MISCELLANEOUS	DEALER STATES THE WALL PANEL IS BULGED OUT AT SEAM ABOVE WINDOW BY THE COUCH	Warranty Pay	\$82.50
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Wall studs are offset from each other. 1.0hr requested.

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$37.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	1.08	1.2	1.2	\$82.50	\$37.20
matthewl	-	0	0	0	\$0.00	\$0.00

1. Pulled the seam tape back. Looks like someone had already messed with it. The wall studs seem to be offset from each other, causing a difference in the wall panels. Pulled the right panel back enough to get a thin shim along the stud and fastened back down in place. Put seam tape over it.

Total Labor Sale \$82.50	Total Labor Cost \$37.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

C. MISCELLANEOUS	DEALER STATES THE COMPARTMENT HARDWARE ON DRIVERS SIDE HAS ADHESIVE STUCK TO THEM	Warranty Pay	\$33.00
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Adhesive on hardware. .20hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16 T8920549

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$6.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.11	0.2	0.2	\$33.00	\$6.20
matthewl	-	0	0	0	\$0.00	\$0.00

1. Cleaned off with adhesive remover.

Total Labor Sale
\$33.00

Total Labor Cost
\$6.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

D. MISCELLANEOUS	DEALER STATES FOUND SEVERAL SPOTS OF SCRATCHED PAINT ON 3 PIECES OF METAL SIDING	Internal Pay	\$0.00
------------------	--	--------------	--------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Metal was scratched during install. 6.50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.63	0	0	\$0.00	\$0.00
matthewl	-	0	0	0	\$0.00	\$0.00

1. Will have to remove 2 windows, the front and rear extrusions, and will need new VIN stickers as they are on one of the pieces that need replacing. Took basic measurements of width of pieces. The length is approximately 18 ft long.

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG16 T8920549	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

E. MISCELLANEOUS	DEALER STATES THE MOLDING ABOVE ENTRY DOOR HAVE ADHESIVE RESIDUE STUCK ON IT	Warranty Pay	\$49.50
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Adhesive on molding. .30hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.28	0.3	0.3	\$49.50	\$9.30
matthewl	-	0	0	0	\$0.00	\$0.00

1. Cleaned off with adhesive remover and plastic scraper.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$49.50	\$9.30	\$0.00	\$0.00

F. MISCELLANEOUS	DEALER STATES BOTH STINK VENTS ARE MISSING THE CAPS	Warranty Pay	\$101.86
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. One of the stink vents did not have the set screw in cap, the other one broke off at the sett screw. .70hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00

Labor Cost: \$14.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.05	0	0	\$0.00	\$0.00
matthewl	-	0.36	0.6	0.6	\$99.00	\$14.40





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG16 T8920549	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00
Labor Cost: \$14.40

1. Will need 2 new stink vents.
2. Matt L: REplaced both stink vent covers. Screwed and glued (sealed).

Parts

Parts Total Sale Amount \$2.86
Parts Total Cost Amount \$2.20

Name	Quantity	Unit Price	Sale Price	Cost Price
390798 - Caps - Vent - Plastic - Black	2	\$1.43	\$2.86	\$2.20

Total Labor Sale \$99.00	Total Labor Cost \$14.40	Total Parts Sale \$2.86	Total Parts Cost \$2.20
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

G. MISCELLANEOUS	DEALER STATES ROOF NEEDS RESEALED IN SEVERAL SPOTS	Warranty Pay	\$60.55
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Caulking was not applied correctly. .20hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.19	0.3	0.3	\$49.50	\$9.30
matthewl	-	0	0	0	\$0.00	\$0.00

1. Resealed roof where needed.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16 T8920549

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$9.30

Parts

Parts Total Sale Amount \$11.05

Parts Total Cost Amount \$8.50

Name	Quantity	Unit Price	Sale Price	Cost Price
08091088 - LAP SEALANT WHT	1	\$11.05	\$11.05	\$8.50

Total Labor Sale
\$49.50

Total Labor Cost
\$9.30

Total Parts Sale
\$11.05

Total Parts Cost
\$8.50

H. MISCELLANEOUS DEALER STATES THE STYLE ON MEDICINE CABINET DOOR IS DAMAGED Warranty Pay \$160.15

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Damaged during install. If getting new door, .20hr requested. If getting just style, .70hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.03	0	0	\$0.00	\$0.00
matthewl	-	0.25	0.2	0.2	\$33.00	\$4.80

1. Will need new cabinet door or style to repair.

2. Taped with approved tape. Looks good.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ASPEN TRAIL 4YDTATG16 T8920549	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Parts

Parts Total Sale Amount \$5.00

Parts Total Cost Amount \$3.85

Name	Quantity	Unit Price	Sale Price	Cost Price
670034 - SEAM TAPE	5	\$1.00	\$5.00	\$3.85

Fees

\$122.15

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$122.15	\$0.00

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$33.00	\$4.80	\$5.00	\$3.85

I. MISCELLANEOUS	DEALER STATES LP CAUTION/WARNING LABELS ARE CRUMPLED AND BARELY ADHERED TO UNIT	Warranty Pay	\$36.87
------------------	---	--------------	---------

Job added by KEVIN GOODIEL on Fri Mar 13, 2026 | 9:51 AM

1. Improper install by manufacturer. .20hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0	0	\$0.00	\$0.00
matthewl	-	0.07	0.2	0.2	\$33.00	\$4.80





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM

Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM

Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16 T8920549

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$4.80

1. Needs new LP warning/caution labels.
2. Installed warning labels.

Parts

Parts Total Sale Amount \$3.87

Parts Total Cost Amount \$2.98

Name	Quantity	Unit Price	Sale Price	Cost Price
673518 - LABEL	1	\$3.87	\$3.87	\$2.98

Total Labor Sale
\$33.00

Total Labor Cost
\$4.80

Total Parts Sale
\$3.87

Total Parts Cost
\$2.98

Category	Sale	Cost
Labor	\$594.00	\$123.90
Parts	\$22.78	\$17.53
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$122.15	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$738.93	\$141.43





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM
Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM
Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16 T8920549

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Thu Apr 2, 2026	12:21 PM	1:18 PM	0.94 hrs	W	lafavet	1 hrs
			Tag: Regular Hour		Reason: -			
B	MISC	Thu Apr 2, 2026	1:27 PM	2:32 PM	1.08 hrs	W	lafavet	1.2 hrs
			Tag: Regular Hour		Reason: -			
C	MISC	Thu Apr 2, 2026	2:33 PM	2:39 PM	0.11 hrs	W	lafavet	0.2 hrs
			Tag: Regular Hour		Reason: -			
E	MISC	Thu Apr 2, 2026	2:40 PM	2:42 PM	0.04 hrs	W	lafavet	0.3 hrs
			Tag: Regular Hour		Reason: -			
F	MISC	Thu Apr 2, 2026	2:46 PM	2:50 PM	0.05 hrs	W	lafavet	0 hrs
			Tag: Regular Hour		Reason: -			
H	MISC	Thu Apr 2, 2026	2:52 PM	2:55 PM	0.03 hrs	W	lafavet	0 hrs
			Tag: Regular Hour		Reason: -			
D	MISC	Thu Apr 2, 2026	3:03 PM	3:32 PM	0.47 hrs	I	lafavet	0 hrs
			Tag: Regular Hour		Reason: -			
E	MISC	Thu Apr 2, 2026	3:45 PM	4:00 PM	0.24 hrs	W	lafavet	-
			Tag: Regular Hour		Reason: -			
G	MISC	Fri Apr 3, 2026	9:00 AM	9:11 AM	0.19 hrs	W	lafavet	0.3 hrs
			Tag: Regular Hour		Reason: -			
D	MISC	Fri Apr 3, 2026	9:23 AM	9:25 AM	0.03 hrs	I	lafavet	-
			Tag: Regular Hour		Reason: -			





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$738.93

RO# : 40259 Tag# : T8920549

Check-in: Fri Mar 13, 2026 | 9:51 AM
Ready for Pickup: Mon Apr 20, 2026 | 10:46 AM
Promise Time: Wed Mar 18, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ASPEN
TRAIL
4YDTATG16 T8920549

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	Fri Apr 3, 2026	9:25 AM	9:28 AM	0.06 hrs	I	lafavet	-
Tag: Regular Hour			Reason: -					
D	MISC	Fri Apr 3, 2026	9:52 AM	9:56 AM	0.07 hrs	I	lafavet	-
Tag: Regular Hour			Reason: -					
F	MISC	Fri Apr 17, 2026	1:18 PM	1:39 PM	0.36 hrs	W	matthewl	0.6 hrs
Tag: Regular Hour			Reason: -					
H	MISC	Fri Apr 17, 2026	1:41 PM	1:56 PM	0.25 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
I	MISC	Fri Apr 17, 2026	2:11 PM	2:15 PM	0.07 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					
I	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
A	MISC	-	-	-	0 hrs	W	matthewl	0 hrs
B	MISC	-	-	-	0 hrs	W	matthewl	0 hrs
C	MISC	-	-	-	0 hrs	W	matthewl	0 hrs
D	MISC	-	-	-	0 hrs	I	matthewl	0 hrs
E	MISC	-	-	-	0 hrs	W	matthewl	0 hrs
G	MISC	-	-	-	0 hrs	W	matthewl	0 hrs
A	MISC	-	-	-	0 hrs	W	shurterc	0.3 hrs

