



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64537

CUSTOMER WORK ORDER

WO #: 64537

Customer: 50923 - SMITH, SR, FLOYD L.
- 270-617-0777

Tag:

Author: BH

Location: 0625 SEND IN TO PREAUTH

Stock #: 10861

Stock Desc: 2021 TT FOREST RIVER
CHEROKEE WOLF PUP 16HE

Chassis #: 5ZT2CKEC4MY012902

Serial #: 5ZT2CKEC4MY012902

Mileage:

Licence:

Invoice #:

Date In: 23 JUN 21

Promised:

Date Sched:

Completed: 25 JUN 21

Warr. Date: 25 FEB 21

Job #1 - Warranty

BATTERY IS NOT HOLDING A CHARGE WHEN BATTERY IS SITTING BY ITSSELF

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	26.00

Parts

Part #	Description	Qty	Price	Total
SRM27	GROUP 27 DC BATTERY	1.00	94.77	94.77

Subtotal for Job #1: 120.77

Parts Total:	94.77
Labour Total:	26.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	120.77

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Jun 2021



Customer #: 50923
SMITH, SR, FLOYD L.

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	656766
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CKEC4MY012902
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	017 / 017D
Labor rate:	\$130.00	ITEM #	CKTR16HE-D
OWNER INFORMATION		DEALER RO #	64537
FLOYD SMITH SR		CLAIM START DATE	06/23/2021
		CLAIM END DATE	01/01/1900
704 HARPER HENDERSON LN			
Hardinsburg, KY 40143			
USA			
Retail Date of Purchase	02/25/2021	WARRANTY EXPIRATION DATE	02/25/2022

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	40-106-01-11-001250	12 Volt Battery - Electrical/12 Volt Exterior/Replace/Electrical			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2021-06-23 13:09:41 :: BATTERY IS NOT HOLDING A CHARGE WHEN BATTERY IS SITTING BY ITSSELF CHARGED THE BATTERY AND WONT HOLD A CHARGE NEED TO REPLACE THE BATTERY				
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$26.00
	Serial #	Appr Hrs	0.20	Appr Labor Amt	\$26.00
	Notes				
	please attach picture of the battery tag				
	PHOTO IS UPLOADED				
	Need to return battery label only with claim submission.				

Submitted	Labor Amt	\$26.00	Approved	Labor Amt	\$26.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$26.00		Total	\$26.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.