

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13524

Date In: 15 MAY 26 Author: KOTT
Promised Date: 25 DEC 26 Stock No: 11046
: Year: 2024
Customer Name: 18044 - WHITFORD, TINA Manufacturer: FOREST RIVER
Address: 515 N WILLOW AVENUE Brand: FLAGSTAFF CLASSIC TT
: MARSHFIELD, WI Model: 826BHS
Postal/Zip: 54449 Miles/Hrs:
Phone#(res): 7158973483 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: tmwhitford18@gmail.com Tag#: DB: 5/18
Purchased Date: 20 APR 26 :
Delivery Date: 05 MAY 26 :
InService Date: :
Serial#: 4X4TFLF27R1906055 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: CUSTOMER JUST PICKED UP THE UNIT AND THE W 1021 FORES
LEVELING SYSTEM IS NOT OPERATING
CORRECTLY- CUSTOMER TRIED
TROUBLESHOOTING WITH LIPPERT OVER THE
PHONE (MANUAL RESETS, ETC-) THE RIGHT
REAR JACK IS NOT GETTING ANY POWER-
NEEDS TO BE LOOKED AT
CAUSE: confirmed customers concern- they had
previously spoken to lippert who
determine that there was no power at the
jack
CORRECTION: will need to R&R the motor for the rear
most jack- req: 2 hours of labor
2 COMPLAINT: CUSTOMER STATES THAT THE BACKSPLASH IS W 1021 FORES
CRACKED AND NEEDS TO BE REPAIRED-
CAUSE: there is a split down the back splash
under the cabinets- the backsplash will
need to be replaced-
CORRECTION: r&r backsplash req: 8 hours of labor-
will need to remove all of the upper
cabinets, the window, and the other
items that are on the surface in order
to install new backsplash.
3 COMPLAINT: CUSTOMER STATES THAT THE VANITY IN THE W 1021 FORES
BATHROOM, THERE IS A PIECE THAT IS
STARTING TO SEPERATE SLIGHTLY- NEEDS TO
BE REATTACHED
CAUSE: The paneling popped loose and needs to

Continued on page 2

