



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72877-1
Promised Date:
18 MAY 26

72877-1

WO #: 72877-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9664 2026 OPEN RANGE
RANGE LITE 270DBL
Serial#: 12M3069
Chassis#: 58TBM0BR6T12M3069
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 18 MAY 26
Time In:

Job #01 - Warranty

COMPLAINT: Rear passenger grease cap is not installed

CAUSE: Grease Cap was not installed properly upon arrival. Upon inspection there is debris in the grease as well as rust on the bearings themselves. Wheel center cap is damaged as well as grease cap

CORRECTION: Replace wheel bearings and racers and pack with new grease Requesting 1.5 hr

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #01:		0.00

Job #02 - Warranty

COMPLAINT: Bedroom door guide on bottom is loose

CAUSE: Bedroom door guide is loose and pulling out from the original mounts
Requesting .25 hr

CORRECTION: New hardware and re install Requesting .25 hr

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #02:		0.00

Job #03 - Warranty

COMPLAINT: Lino on bottom of ladder by entrance is bullion

CAUSE: Lino on bottom of ladder by entrance is bullion due to the floor it self being cut wrong

CORRECTION: Need to remove ladder then re cut Lino to fit around the base of the ladder then glue around area of ladder and let dry then re attach the ladder
Requesting 1 hr

Labor

Job #	Description	Total
03	MISC LABOUR CODE (WARRANTY)	N/C

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

W/O: 72877-1
Promised Date: 15 MAY 26

72877-1

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

Subtotal for Job #03: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 18 May 2026

Customer Signature : _____