



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79577
Promised Date:
20 MAY 26



CUSTOMER WORK ORDER

WO #: 79577

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0520 CHECK PREAUTH

Stock #: 11729
Stock Desc: 2026 5W KEYSTONE
MONTANA 3100RL
Chassis #: 4YDFM0R22T4700700
Serial #: 4YDFM0R22T4700700
Mileage: 0
Licence:

Invoice #:
Date In: 14 APR 26
Promised: 30 MAY 26
Date Sched:
Completed: 20 MAY 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: 26-482 Montana Underbelly Securement Recall It has been decided that the vehicles in the recall population may have inadequate securement of the underbelly to the drop-down section of the frame. Under certain conditions during travel, the underbelly may come loose or detach from the vehicle, leading to an increased risk of a vehicle crash.

CAUSE: there are multiple tears in the underbelly where they are secured to the frame. also,there are no crossmembers to attach self tapping screws to secure the middle section of the underbelly. tech recommends removing the damages underbelly and replacing it. we will also need crossmembers to complete the recall. 7ft x 9ft underbelly

CORRECTION: Closed the slide rooms and pulled the unit up to the shop. Removed rivets and screws from the frame and removed the underbelly. Took the new underbelly material and cut to length. Secured the underbelly with self tapping screws and washers. Measured and secured the cross members at 60 and 90 inches from the front.. Installed front and rear aluminum bracing. Cleaned up tools and parked unit. Typed notes and put the remaining underbelly up.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	95.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	95.00
Z990	MISCELLANEOUS REPAIR	ZMS	95.00
Z990	MISCELLANEOUS REPAIR	ZMS	95.00

Parts

Part #	Description	Qty	Price	Total
13183	WOVEN UNDERBELLY - 74"w X LENGTH - S	56.00	1.04	58.24
790039	Crossmember - C Channel - 72 1/8" x	2.00	28.41	56.82

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-UNDERBELLY	1.00	119.98	119.98

Subtotal for Job #1: 615.04

Job #2 - Warranty

COMPLAINT: SHOCK ON THE DOOR SIDE REAR TIRE HAS FELL OFF

CAUSE: The bolt that holds the shock together is missing. A strut was ordered. Took a bolt off another strut because we couldnt get one from warranty went out to the unit and found the bolt is broken and is stuck inside the hanger.

Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: The broken bolt was removed. A replacement bolt and washer were installed.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	38.00
Z990	MISCELLANEOUS REPAIR	ZMS	19.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
771236	Axle - Shock - TCS - 12.63" - EXT LG	1.00	116.14	116.14

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SHOCK	1.00	12.57	12.57

Subtotal for Job #2: 185.71

Job #3 - Warranty

COMPLAINT: REMOVE THE BOLT WITH THE BROKEN HEAD ON THE FRONT DOOR SIDE AXLE SHOCK

CAUSE: Bolt is snapped off of shock mount.

CORRECTION: I drilled the bolt and extracted it.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	GAH	57.00

Subtotal for Job #3: 57.00

Parts Total: 231.20
 Labour Total: 494.00
 Sublet Total: 0.00
 Extras Total: 132.55
WORK ORDER TOTAL: 857.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 May 2026

W/O: 79577
Promised Date: 30 MAY 26



Customer #: 1000
BASDENS AMERICAN RV,

