



# KEYSTONE

## Pre-Authorization

Pre-Authorization number	PREAUTH106 148 (PA03997232	Reference no.79577	Status	Approved
--------------------------	----------------------------------	--------------------	--------	----------

**Servicing Dealer** 1194     
 **Name** Basden's American RV     
 **Address** 600 E Baseline Rd  
 Evansville, IN 47725     
 **VIN** 4YDFM0R22T4700700     
 **Retail sold on**

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
	1102114B Shock Absorber	0	0.3	0.3		1	0.2	<b>Complaint:</b> SHOCK ON THE DOOR SIDE REAR TIRE HAS FELL OFF <b>Cause:</b> The bolt that holds the shock together is missing. <b>Correction:</b> REMOVE OR REPAIR
	1102308B Shock Absorber - Lower Mounting Bracket	0	0.5	0.3		1	0.3	KRV - approved to replace <b>Complaint:</b> REMOVE THE BOLT WITH THE BROKEN HEAD ON THE FRONT DOOR SIDE AXLE SHOCK <b>Cause:</b> Bolt is snapped off of shock mount. <b>Correction:</b> I drilled the bolt and extracted it.
	Pre-authorization number: PREAUTH106148			0.6				

For paper claims only use one pre-authorization number per warranty claim form.  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.