

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13017

Date In:	17 OCT 25	Author:	DLUCAS
Promised Date:	31 MAY 26	Stock No:	11259
:	:	Year:	2025
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	402LFT
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	11/19- parts inquiry
Purchased Date:	21 JUN 25	:	:
Delivery Date:	28 JUN 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS2XSP104319	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
SC	SERVICE CALL TO CUSTOMERS PROPERTY:	1003 MOOR CRT	E	122926 MCDON
1	COMPLAINT:	CUSTOMER STATES WATER HEATER IS STILL THROWING CODES AND WHEN GOING TO LIGHT IT IT LIGHTS FOR A SECOND AND THEN GOES OUT AND SHUTS OFF AND DOESNT TRY TO RESTART (PROBLEM IS RANDOM WORKS SOMETIMES DOESNT WORK OTHERS SEEMS LIKE FLAME SENSE IS BAD)**TAPPED ON THE SOLENOIDS ON LEFT SIDE WITH SCREW DRIVER AND HAS BEEN WORKING SINCE** **HAS BEEN IN CONTACT WITH LIPPERT**	W	1021 FORES
	CAUSE:	when trying the water heater multiple times it didn't come on it was throwing a e2 code i banged on gas valve and then ran water it came on customers needs a new water heater also taken pic of front left motorized shade that needs replacing due to pin hole in fabrics and slipping as it extended also on left side there's a standard shade has a pin hole needs replacing		
	CORRECTION:	dis assemble the front of water heater pics taken I removed and installed the new gas valve for tankless water heater reverse the process putting together I also checked new gas valve for leaks that's ok and also tested water heater after repairs is now working with no		

Continued on page 2

Work Order : 13017

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                codes
2      COMPLAINT:  Customer states pinholes in fabric of      W    1021    FORES
                shade at front on unit on left side of
                couch
                CAUSE:    on off door side front left shade
                replacement pic taken after install
                CORRECTION: remove and install the smaller shade is
                correct and tested ok
3      COMPLAINT:  CUSTOMER STATES PINHOLES IN FRONT          W    1021    FORES
                MOTORIZED SHADE BEHIND COUCH
                CAUSE:    mfg sent a non motorized shade I need
                one with motorized pics should already
                be in work order this shade is in very
                front of unit it's the bigger size one
                CORRECTION: need correct shade motorized
4      COMPLAINT:  CUSTOMER STATES SEAM IN GUTTERS LEAKS      W    1021    FORES
                ICE COMING DOWN OVER WINTER CRACKED
                FENDER SKIRTS
                CAUSE:    pics taken of both fender skirts will
                need to be replaced due to cracking also
                took pics of awning the tube is sagging
                in middle and fabric is all bunched up
                new awning fabric and tube
                CORRECTION: I did seal off gutters tracks seams with
                non leveling black dicor

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty    Price    Total
*****
3      82205364  SHADE ROLLER 27X72 BAMBOO B W-1021      1      61.78     61.78
1      82207554  GAS VALVE 2GWH-2          W-1021      1     142.03    142.03
2      822090882 ROLLER SHADE 20 X 42      W-1021      1      41.72     41.72
4      822013905 CLAMP RING, 532 (40x12) 11. W-1021      1      32.18     32.18

```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to   Hrs    Rate    Total
*****
1 WARR      MANUFACTURER WARRANTY JS    W-1021      0.50   140.00    70.00
2 WARR      MANUFACTURER WARRANTY JS    W-1021      0.50   140.00    70.00
3 WARR      MANUFACTURER WARRANTY JS    W-1021      0.50   140.00    70.00
4 WARR      MANUFACTURER WARRANTY JS    W-1021      0.50   140.00    70.00
1 WARR      MANUFACTURER WARRANTY JS    W-1021      0.50   140.00    70.00

```

```

*****
Job # Excode   Description    EXTRAS      bill to   Qty    Price    Total
*****
SC SC      SERVICE CALL          E-122926  15.00     3.75     56.25
3 FRT      FREIGHT              W-1021     0.00     0.00      0.00
2 FRT      FREIGHT              W-1021     1.00    45.99    45.99

```

Continued on page 3

Work Order : 13017

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	122926	0.00	0.00	0.00	56.25	3.11	59.36
W	1021	277.71	350.00	0.00	45.99	0.00	673.70
	Totals	277.71	350.00	0.00	102.24	3.11	733.06

&k2S
&k0S