



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79592



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 79592

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0501 CHECK STATUS WITH
PCG

Stock #: 11740
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 23MK
Chassis #: 4X4TCKY27TK099781
Serial #: 4X4TCKY27TK099781
Mileage: 0
Licence:

Invoice #:
Date In: 15 APR 26
Promised:
Date Sched:
Completed: 30 APR 26
Warr. Date: 27 APR 26

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New PDI

CORRECTION: Torqued lugs to spec. Adjusted tire pressures to spec. Installed company decals. Checked exterior Lights. Checked braking and emergency breakaway systems. Checked all exterior seals. Checked exterior doors for fit and finish. Checked slide room function. Checked awning function. Checked sidewalls. Performed roof inspection. Checked stabilizer and tongue jacks. Interior; checked all interior lights. Checked blinds and window operation. Inspected all interior doors. Inspected flooring. Inspected drawers, cabinets, and closets. Tested all appliances. Tested water system on city and pump. Tested all LP systems. Tested antenna. Performed LP drop test. Issues; door side shower head leaking. Slide not coming in all the way. Screen door latch on entry door needs adjusting. Door latch sticking

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: DOORS ABOVE STOVE ARE HITTING EACH OTHER

CAUSE: Doors spaced too close

CORRECTION: Adjusted doors slightly to have a small gap

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	58.50



Subtotal for Job #1: 58.50

Job #2 - Warranty

COMPLAINT: OUTSIDE FRIDGE IS DENTED

CAUSE: Dented in transit

CORRECTION: Replace door or fridge

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	29.25
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	29.25

Parts

Part #	Description	Qty	Price	Total
12533	Hotpoint RV Mini Refrigerator w/ Fre	1.00	233.27	233.27

Subtotal for Job #2: 291.77

Job #3 - Warranty

COMPLAINT: DOOR SIDE SHOWER HEAD LEAKING

CAUSE: Shower head cracked

CORRECTION: Replaced head

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	15.60
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	3.90

Parts

Part #	Description	Qty	Price	Total
60P04230A	SHOWER, SHOWER HEAD W/ HOSE- WHITE	1.00	1.31	1.31

Subtotal for Job #3: 20.81

Job #4 - Internal

COMPLAINT: SLIDE NOT COMING IN ALL THE WAY

CAUSE: Lack of proper voltage from forktruck

CORRECTION: Tested on shore power and slide worked properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: THE SCREEN DOOR LATCH ON THE ENTRY DOOR NEEDS ADJUSTED

CAUSE: Latch adjusted too far down

CORRECTION: Moved latch up

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

W/O: 79592



Customer #: 1000
BASDENS AMERICAN RV,



Subtotal for Job #5: 39.00

Job #6 - Warranty

COMPLAINT: THE ENTRY DOOR LATCH IS STICKING

CAUSE: Door plate installed backwards

CORRECTION: Installed plate correctly

Labor Code	Description	Mechanic PCG	Total
Z990	MISC LABOUR CODE (EXTERNAL)		39.00

Subtotal for Job #6: 39.00

Parts Total: 234.58
Labour Total: 214.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 449.08

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 May 2026

W/O: 79592



Customer #: 1000
BASDEN'S AMERICAN RV,

