



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79838



CUSTOMER WORK ORDER

WO #: 79838

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0529 CHECK WORK

Stock #: 11732
Stock Desc: 2026 TT COACHMEN
REMOTE 12.3R
Chassis #: 5ZT2RMAC9TL019677
Serial #: 5ZT2RMAC9TL019677
Mileage: 0
Licence:

Invoice #:
Date In: 06 MAY 26
Promised:
Date Sched:
Completed: 07 MAY 26
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 2 HR PDI

CAUSE: New PDI

CORRECTION: Exterior; Torqued lugs to spec. Adjusted tire pressures to spec. Checked braking and emergency breakaway systems. Checked awning and awning light function. Checked clearance lights. Inspected exterior walls and seals. Installed battery box. Installed company decals. Filled and installed LP cylinders. Checked all other exterior lights. Performed roof inspection. Checked stabilizers. Inspected exterior doors for fit and finish. Checked entry steps.

Interior; checked all interior lights. Checked smoke detector and LP detector. Tested windows and curtains. Tested all appliances. Tested entire LP system. Checked Interior walls, ceiling, and floors. Checked water system on pump and city connection. Checked waste drains. Checked outlets and charging ports.

Issues; screen door drags. Entry door drags.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	PCG	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR IS DRAGGING

CAUSE: Entry door bowed

CORRECTION: Bent entry door back to straight and adjust striker plate

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	58.50

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 58.50

Job #2 - Warranty

COMPLAINT: SCREEN DOOR IS DRAGGING

CAUSE: Screen door was bent slightly

CORRECTION: Adjusted screen door back to proper position

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	PCG	39.00

Subtotal for Job #2: 39.00

Parts Total: 0.00
Labour Total: 97.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 97.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 May 2026

W/O: 79838



Customer #: 1000
BASDENS AMERICAN RV,

