

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS Authorized
BASDEN RV CENTER INC		CLAIM 2602775
DBA AMERICAN RV CENTER		CLAIM ORIGIN WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID
EVANSVILLE, IN 47725		VIN 5ZT2FEKB7SW030811
USA		CHASSIS VIN
		MILEAGE 0
Labor rate: \$195.00		SITE/WAREHOUSE 320 / 320
OWNER INFORMATION		ITEM # FET21SE-320
SARAH A FISCHER		DEALER RO # 79143
2100 REIS LANE		CLAIM START DATE 03/09/2026
Wadesville, IN 47638		CLAIM END DATE 01/01/1900
USA		
Retail Date of Purchase 03/06/2026	WARRANTY EXPIRATION DATE 03/06/2027	

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-106-24-11-001253	Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-09 08:57:02 :: REAR RED SIDE MARKER LIGHT NOT WORKING Right rear light doesn't work Took light off and the wires was on the wrong wires. So i tested witch wire was power and negative and wired them up correctly and it works properly			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$19.50
	Serial#	Appr Hrs	0.10	Appr Labor Amt \$19.50
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	40-106-01-12-001216	Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-09 08:57:46 :: FRONT AMBER MARKER LIGHT NOT WORKING Front left amber running light doesn't work Took light off and tested it i had power there but light doesn't work so i got a new light and installed it and wired it up and new light works properly now			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt\$39.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-03-09 08:59:21 :: OUTSIDE HOT WATER CONNECTER THAT RUNS TO THE FAUCET HAS A CRACK IN IT Outdoor kitchen water line leaking On inspection of the outside kitchen noticed a leak at the connection. Try a new cone washer it didnt fix it so then i installed a new connector and got it crimped on and no leak. All good now			
	Model#	Dlr Sub Hrs	0.25	Sub Labor Amt \$48.75
	Serial#	Appr Hrs	0.25	Appr Labor Amt \$48.75
	Notes			

Labor

Line# 4	Operation Code	Operational Description
	30-99-01-00-001012	Mini-Blind - Interior/Soft Goods/Replace/No Tread Code
	Complaint, Cause, Correction	

Original Note : bhoffman@americanrvcenter.com, 2026-03-09 09:02:21 :: WINDOW BLIND IS DAMAGED THE STRING WAS PULLED THROUGHT THE PLASTIC AND IS DAMAGED THE BLIND NEED TO REPLACE

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$39.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$39.00

Notes

Labor

Line# 5	Operation Code	Operational Description
	70-167-01-00-001997	Water Heater Door - Appliances/Water Heater (Suburban)/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-03-09 09:02:59 :: WATER HEATER DOOR IS RUSTED. Water heater door has rest on it I took the rusty door off and replaced it with a new one. I put budle tape on the back of the door and new screws and sealed the outside with clear silicone.

Model# ST-42	Dlr Sub Hrs	0.50	Sub Labor Amt	\$97.50
Serial# 245000507S	Appr Hrs	0.30	Appr Labor Amt	\$58.50

Notes

R&R suburban water heater door due to rust as per flat rate = 0.30; vcb

Submitted	Labor Amt	\$243.75	Approved	Labor Amt	\$204.75
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$243.75		Total	\$204.75

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.