

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2646184
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY27TK099781
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT23MK-94
		DEALER RO #	79592
		CLAIM START DATE	04/17/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-100-24-00-001046	Operational Description Cabinet Door - Interior/Cabinetry/Repair/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-17 14:56:53 :: DOORS ABOVE STOVE ARE HITTING EACH OTHER Doors spaced too close Adjusted doors slightly to have a small gap	
Model#	Dlr Sub Hrs	0.30
		Sub Labor Amt \$58.50
Serial#	Appr Hrs	0.30
		Appr Labor Amt \$58.50
	Notes	

Labor

Line# 2	Operation Code 70-675-01-11-003364	Operational Description Hotpoint Mini Refrigerator - Appliances/Mini Refrigerator (Hotpoint)/Replace/Electrical
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-17 14:57:29 :: OUTSIDE FRIDGE IS DENTED Dented in transit Replace door or fridge	
Model# NA	Dlr Sub Hrs	0.30
		Sub Labor Amt \$58.50
Serial# NA	Appr Hrs	0.30
		Appr Labor Amt \$58.50
	Notes	

If a complete replacement is authorized, do not dispose of the unit. The cut power cord and the physical data tag may be required back for warranty coverage. Please wait to cut the cord until the repair is authorized and the Dealer has been instructed to do so.

This code requires the Dealer to enter the product's model and serial numbers in the appropriate claim fields. A picture of the data tag with the model/serial numbers is recommended and helpful.

replace

Labor

Line# 3	Operation Code 60-141-01-00-001618	Operational Description Shower Head, Hose Assembly - Plumbing/Shower, Tub Surround/Replace/No Tread Code
	Complaint, Cause, Correction	
	Original Note : bhoffman@americanrvcenter.com, 2026-04-17 14:58:13 :: DOOR SIDE SHOWER HEAD LEAKING FOUND LEAKING AND NEEDS REPALCED	
Model#	Dlr Sub Hrs	0.10
		Sub Labor Amt \$19.50
Serial#	Appr Hrs	0.10
		Appr Labor Amt \$19.50
	Notes	

Line# 4

20-66-24-00-002294

Screen Door - Exterior/Entry Doors/Repair/No Tread Code

Original Note : bhoffman@americanrvcenter.com, 2026-04-17 14:59:28 :: THE SCREEN DOOR LATCH ON THE ENTRY DOOR NEEDS ADJUSTED Latch adjusted too far down Moved latch up

Sub Labor Amt \$39.00

Appr Labor Amt \$39.00

Line# 5

20-66-02-17-000672

Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch

Original Note : bhoffman@americanrvcenter.com, 2026-04-17 15:00:00 :: THE ENTRY DOOR LATCH IS STICKING
Door plate installed backwards Installed plate correctly

Sub Labor Amt \$39.00

Appr Labor Amt \$39.00

Submitted

Approved

\$214.50

Parts & Freight

Total

\$214.50

DEALER

DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.