

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79652
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56540 - SARAH FISCHER
Address: 2100 REIS LN WADESVILLE, IN

47638

Phone: 812-550-5670

Stock Number: 11559 - 2025 FREEDOM EXPRESS 21SE 5ZT2FEKB7SW030811

VIN: 5ZT2FEKB7SW030811 HIN: SER#: 5ZT2FEKB7SW030811

Mileage: 0 Work Order Comp: 07 MAY 26

Auth. No: Dealer #:

Warr. Date: 06 MAR 26 Work Order Date: 21 APR 26 Inv #: 429791

WO # Job # Description JOB INFORMATION

79652 2 Light over sink flickers - could be a loose led?
 Light over sink flickers
 So i took the light out and took off the connectors and checked
 the wires. I stripped two of the wires a little bit more and put
 new connectors on. But the longer you leave the light on it
 starts to flicker. I checked the voltage and it was good at the
 light. So i put in a parts request for a new light

79652 3 Outdoor sink cold line leaks underneath and it drips fairly often
 from the faucet - tried tightening but I think there's a plastic
 piece that was broken.
 Outdoor kitchen cold line leaks
 I pressurize the system and seen the cold line drip. So i took it
 apart and the fitting may have a crank. So i replaced the fitting
 and i cut some off the hose to make a good seal. And tested it on
 pump and city no leaks

79652 7 INSIDE KITCHEN FAUCET IS LEAKING ON THE HOT SIDE
 Hot water line under kitchen sink leaks
 When i was hooked up to city water working on the outdoor kitchen
 leakthat the hot line was leaking. So i took it apart and seen
 the from the factory the cone washer was installed incorrectly.
 So i put a. Ew cone washer in and pressurized the system and no
 leaks.

79652 1 THE ANTENNA CORD BROKE AND DETACHED FROM THE TV

Claim : 79652

 WO # Job # Description JOB INFORMATION

Coax cable broke
 Took off broken cable and replaced it with a new one. I put new
 ends on the cable

79652 4 Outdoor sink water drain line leaks at white joint coupler -
 tried tightening but it was still leaking.
 Outdoor kitchen drain leaks
 Pressurized system and ran water through the drain and i seen it
 leak. So i went ahead and took the drain apart and made sure the
 rubber hose was pushed up were it neede to be and put some dope
 on the threads and made sure it screwed on properly and tightened
 the joint and checked it again for leaks. And no leaks. I tested
 it on pump and city water pressure

79652 6 THE OUTDOOR KITCHEN DOES NOT LOCK
 Outdoor kitchen door hard to lock.
 After inspection of the door lock and you had to push in on the
 door. I changed the lock blade and it locks easily now

 Part No Job# Description PARTS Qty Price Total

 F100618014 2 LIGHT, RV LED WAFER SLIM W/DIMMAB 1.00 8.78 8.78
 681487 3 1/2" BARB X 1/2 FPT SWIVEL CONE 1.00 2.24 2.24
 10-7150 7 CONE WASHER SWIVEL SEAL 1.00 0.31 0.31

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.10 195.00 19.50

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 UPS-LIGHT 1.00 16.77 16.77

Parts Total: 11.33
 Labour Total: 253.50
 Sublet Total: 0.00
 Extras Total: 16.77

>>>> Claim Total: 281.60

Customer Signature: _____

Date: _____