

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2666963
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TFLY29PZ188259
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010D
 ITEM # FLT233S
 DEALER RO # 13190B
 CLAIM START DATE 05/06/2026
 CLAIM END DATE 05/11/2026

Labor rate: \$140.00

OWNER INFORMATION

MICHAEL SANKEY
 5627 COUNTY ROAD K
 Amherst, WI 54406
 USA

Retail Date of Purchase 04/29/2026

WARRANTY EXPIRATION DATE

04/29/2027

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 40-196-01-11-001277 Ceiling Décor Light - Electrical/12 Volt Interior/Replace/Electrical
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-05-06 16:23:27 :: Complaint: Dinette light not working properly. Cause: Dinette light not working due to broken switch. Correction: Replaced the switch with one we had in the warranty cage.

Model# 1	Dlr Sub Hrs	0.40	Sub Labor Amt	\$56.00
Serial# 1	Appr Hrs	0.40	Appr Labor Amt	\$56.00

Notes

We have updated the repair code to a more appropriate one based on the identified root cause of this repair request

Part

Line# 1	Item #	Description			
	USERPART	shop supplies - switch for light			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$2.80	Sub Freight	\$0.00	
	Appr Qty 1.00	Appr Dlr Price \$2.80	Appr Freight	\$0.00	

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-78-15-00-004588 Arm Bracket - Exterior/Awnings (Lippert)/Repair or Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2026-05-06 16:25:57 :: Complaint: Front awning arm pitch keeps falling down and will not hold the weight of the awning. Cause: The front awning arm kept pitching from the weight of the awning. Correction: Put a new lock washer in and it now holds.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$28.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$28.00

Notes

Part

Line# 1	Item #	Description			
	F100091840	BED PART - PFL: SOCKET ONLY, FOR BED BOW - V# PH-112			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$0.64	Sub Freight	\$19.50	
	Appr Qty 1.00	Appr Dlr Price \$0.64	Appr Freight	\$19.50	

Notes

Submitted	Labor Amt	\$84.00
	Parts & Freight	\$22.94
	Total	\$106.94

Approved	Labor Amt	\$84.00
	Parts & Freight	\$22.94
	Total	\$106.94

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.