



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72854-1
Promised Date:
21 MAY 26

72854-1

WO #: 72854-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9658 2026 AVENGER
16BHX
Serial#: 815524
Chassis#: 5ZT2AVEC9TG815524
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 21 MAY 26
Time In:

Job #01 - Warranty

COMPLAINT: Sticker drivers side and stickers in front of the unit avenger is peeling off of the corners.

CAUSE: Unknown

CORRECTION: Stickers FR are peeling off at ends. The stickers FR need to be replaced and taken off. The panel where the stickers are need to be cleaned and have the adhesive taken off. New stickers need be ordered. The new stickers need to be placed in the factory location.

Photos attached

Request 45 min.

The old stickers on the front need to come off and the adhesive needs to be taken off and paneling cleaned. The new sticker named avenger needs to be ordered. Once the new sticker comes in it can be installed in the factory location.

Photos attached 5/18/26

Requesting 1 hour

Labor

Job #	Description	Total
01	Sticker replacement MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #01:		0.00

Job #03 - Warranty

COMPLAINT: Front panel damaged

CAUSE: Unknown

CORRECTION: Front bottom panel is damaged and has come off partially. You can see the damage where it is dented and outward period part needs to be taken off and see why it is damage from inside out side rails have to come off, adhesive and silicone has to come off. All screws holding the side panel bottom panel and the side rails have to come off. A new bottom panel needs to be ordered and needs to be replaced. Once the panel comes in to the shop the side rails need to be siliconed and screwed in correctly and the front panel needs to be screwed in.

Diag time is approximately one hour to see what damage has been done in the inside behind the panel.
5-19-26

2x2x 87 1/4 Wood under front panel adhesive has pulled away from interior wall and has bowed. Staples need to be removed carefully so that no damage is done to upper panel. New wood has to be glued back to factory location. Upper panel has to be stapled back new wood.

Photos attached

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

Request 4.5 hours

Labor		
Job #	Description	Total
03	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #03:		0.00
Parts Total:		0.00
Labour Total:		0.00
Sublet Total:		0.00
Extras Total:		0.00
WORK ORDER TOTAL:		0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____ Date: 21 May 2026

W/O: 72854-1
Promised Date: 24 APR 26

72854-1

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000